



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26329



WO #: 26329

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11238  
Stock Desc: 2026 C FOREST RIVER FORESTER  
3251DSLEF  
Model: 3251DSLEF  
Serial #: 1FDXE4FNXTDD23815  
Chassis #: 1FDXE4FNXTDD23815  
Mileage: 1000  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 04 NOV 25  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: ALL SEALANT ON ROOF AROUND EDGES AND COMPONENTS (AC, VENTS ETC.) IS LIFTING AND ALLOWING WATER AND MOISTURE IN UNDER ROOF MATERIAL.

CAUSE: SEALANT FROM FACTORY ISN'T ADHERING PROPERLY AFTER INSTALLATION ON THE FOLLOWING: 1 SKYLIGHT, 2 VENTS, FRONT CAP AND EDGES

CORRECTION: CURRENT SEALANT ON ROOF EDGES AND COMPONENTS NEED TO BE SCRAPED AND NEW SEALANT APPLIED

LABOR  
LABOR 4.0

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: DRIVER SIDE DECALS ON SLIDE OUT IN SEVERAL SPOTS ARE DAMAGED. 2 DECALS

CAUSE: DRIVER SIDE OF THE UNIT ON THE SLIDE OUT HAS DAMAGE FROM THE FACTORY INSTALL

CORRECTION: REMOVE CURRENT DECALS, CLEAN AREA AND REPLACE WITH NEW DECALS, TWO DECALS  
LABOR 2.0

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: DRIVER SIDE SLIDE OUT HAS VISIBLE MARKS, SWIRLS AND SPOT WHERE THE CLEAR COAT HAS BEEN DAMAGED FROM FACTORY

CAUSE: NOTED ON DAF  
IMPROPER BUFFING OR POLISHING DURING FINISHING OF PRODUCTION

CORRECTION: REPAIR PREVIOUS BODY WORK. SAND, PAINT, BLEND, ADD CLEAR COAT AND CLEAN AREA  
LABOR 4.0

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #3: 0.00

**Job #4 - Warranty**

COMPLAINT: BATHROOM CABINET HAS NAIL/STAPLE HOLES THAT LOOK LIKE THE PANELS ARE DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: HOLES NEED FILLED, COLOR AND BLENDED TO MATCH AND SO THE HOLES DO NOT LOOK LIKE DAMAGE  
LABOR .40

Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: EXTERIOR SLIDE FASCIA AT THE BOTTOM IS CRACKED AND CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE EXTERIOR BOTTOM SLIDE FASCIA, SEAL AREA ALONG THE TOP AND SIDES OF THE FASCIA  
LABOR 2.5

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: KNOBS ON CABINETS OVER KITCHEN SINK ARE SCRATCHED AND DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE KNOBS ON KITCHEN CABINETS DOORS  
LABOR .30

Subtotal for Job #6: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 10 Nov 2025

Customer Signature : \_\_\_\_\_

Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

