



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 26351

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11242

Stock Desc: 2026 DT FOREST RIVER SANDPIPER
41DUPLEX

Model: 41DUPLEX

Serial #: 4X4TSAS20TJ048926

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 06 NOV 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 21 NOV 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: TRIM ON INSIDE OF HIDDEN PANTRY NOT INSTALLED

CAUSE: TRIM WAS LAYED IN THE PANTRY AND NOT INSTALLED TO COVER WHERE THE PANEL DIDN'T FIT CORRECTLY

CORRECTION: SECURE TRIM IN PLACE TO COVER WHERE PANEL DIDN'T COVER THE BOTTOM OF THE SHELF

LABOR .20

Labor

Job #	Description	Hours	Total
1	RESECURED	0.20	33.00

Subtotal for Job #1: 33.00

Job #2 - Warranty

COMPLAINT: REAR BATHROOM DOOR HAS SCRATCHES AND A SPOT PEELED BACK AT THE TOP

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	FILL AND COLOR	0.30	49.50

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLY	1.00	5.99	5.99

Subtotal for Job #2: 55.49

Job #3 - Warranty

COMPLAINT: REAR BEDROOM DRAWER HAS SCUFS

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND THE AREA

LABOR .20

W/O: 26351



Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
3	COLOR AREA	0.20	33.00
Subtotal for Job #3:			33.00

Job #4 - Warranty

COMPLAINT: REAR BEDROOM DOOR CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor			
Job #	Description	Hours	Total
4	FILL AND COLOR	0.20	33.00
Subtotal for Job #4:			33.00

Job #5 - Warranty

COMPLAINT: CEILING LIGHT OVER SEATING INSTALLED SIDEWAYS

CAUSE: NOTED ON DAF
INSTALLED AT BUILD SIDEWAYSCORRECTION: SECURE LIGHT IN CORRECT PLACE
LABOR .10

Labor			
Job #	Description	Hours	Total
5	SECURED LIGHT	0.20	33.00
Subtotal for Job #5:			33.00

Job #6 - Warranty

COMPLAINT: REAR LOFT CARPET HAS A WRINKLE STICKING UP ACROSS THE ENTIR FLOOR

CAUSE: NOTED ON DAF
CARPAET NOT PULLED TIGHT ENOUGH WHEN INSTALLEDCORRECTION: PULL CARPET TIGHT AND SECURE
LABOR .30

Labor			
Job #	Description	Hours	Total
6	PULLED CARPET TO FIT	0.30	49.50
Subtotal for Job #6:			49.50

Job #7 - Warranty

COMPLAINT: FRONT BATHROOM CABINET BOTTOM HINGE IS NOT SECURE AND ALLOW DOOR TO DROP DOWN

CAUSE: NOTED ON DAF

CORRECTION: RESECURE HINGE IN PLACE AND ADJSUT IF NEEDED
LABOR .30

Labor			
Job #	Description	Hours	Total
7	RESECURED HINGE	0.30	49.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #7: 49.50

Job #8 - Warranty

COMPLAINT: STILE NEXT TO THE SLIDING DOOR IS INSTALLED WRONG. THIS MAKES THE STILE LOOK LIKE IT IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE STILE AND RESECURE IN PLACE CORRECTLY
LABOR .30**Labor**

Job #	Description	Hours	Total
8	RESECURED IN PLACE	0.30	49.50

Subtotal for Job #8: 49.50

Job #9 - Warranty

COMPLAINT: FRONT BEDROOM CABINET DOOR IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND NBLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
9	FILL AND COLOR	0.30	49.50

Subtotal for Job #9: 49.50

Job #10 - Warranty

COMPLAINT: WALL PANEL IN THE FRONT BEDROOM DAMAGED AT THE BOTTOM IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND BOTH AREAS
LABOR .50**Labor**

Job #	Description	Hours	Total
10	FILL AND COLOR	0.50	82.50

Subtotal for Job #10: 82.50

Parts Total:	0.00
Labour Total:	462.00
Sublet Total:	0.00
Extras Total:	5.99

WORK ORDER TOTAL: 467.99

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Nov 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,