



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26351



WO #: 26351

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11242
Stock Desc: 2026 DT FOREST RIVER SANDPIPER
41DUPLEX
Model: 41DUPLEX
Serial #: 4X4TSAS20TJ048926
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 06 NOV 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: TRIM ON INSIDE OF HIDDEN PANTRY NOT INSTALLED

CAUSE: TRIM WAS LAYED IN THE PANTRY AND NOT INSTALLED TO COVER WHERE THE PANEL DIDN'T FIT CORRECTLY

CORRECTION: SECURE TRIM IN PLACE TO COVER WHERE PANEL DIDN'T COVER THE BOTTOM OF THE SHELF
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR BATHROOM DOOR HAS SCRATCHES AND A SPOT PEELED BACK AT THE TOP

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: REAR BEDROOM DRAWER HAS SCUFFS

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND THE AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: REAR BEDROOM DOOR CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CEILING LIGHT OVER SEATING INSTALLED SIDEWAYS

CAUSE: NOTED ON DAF
INSTALLED AT BUILD SIDEWAYS

CORRECTION: SECURE LIGHT IN CORRECT PLACE
LABOR .10

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: REAR LOFT CARPET HAS A WRINKLE STICKING UP ACROSS THE ENTIR FLOOR

CAUSE: NOTED ON DAF
CARPAET NOT PULLED TIGHT ENOUGH WHEN INSTALLED

CORRECTION: PULL CARPET TIGHT AND SECURE
LABOR .30

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: FRONT BATHROOM CABINET BOTTOM HINGE IS NOT SECURE AND ALLOW DOOR TO DROP DOWN

CAUSE: NOTED ON DAF

CORRECTION: RESECURE HINGE IN PLACE AND ADJSUT IF NEEDED
LABOR .30

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: STILE NEXT TO THE SLIDING DOOR IS INSTALLED WRONG. THIS MAKES THE STILE LOOK LIKE IT IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE STILE AND RESECURE IN PLACE CORRECTLY
LABOR .30

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: FRONT BEDROOM CABINET DOOR IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND NBLEND AREA
LABOR .20

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: WALL PANEL IN THE FRONT BEDROOM DAMAGED AT THE BOTTOM IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND BOTH AREAS

W/O: 26351



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .50

Subtotal for Job #10: 0.00

W/O: 26351

| | |
|--------------------------|-------------|
| Parts Total: | 0.00 |
| Labour Total: | 0.00 |
| Sublet Total: | 0.00 |
| Extras Total: | 0.00 |
| WORK ORDER TOTAL: | 0.00 |

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 06 Nov 2025



Customer Work Order

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

