



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26353



WO #: 26353

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11236

Stock Desc: 2026 C FOREST RIVER FORESTER

2851SLEF

Model: 2851SLEF

Serial #: 1FDXE4FN9TDD23756

Chassis #: 1FDXE4FN9TDD23756

Mileage: 1045

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 06 NOV 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 21 NOV 25

Warr. Date:

### Job #1 - Warranty

COMPLAINT: CHIP IN THE PAINT ON DRIVER SIDE DOOR

CAUSE: NOTED ON DAF

CORRECTION: THIS WILL NEED TO BE FILLED, SAND AREA, PAINT AND CLEAR COAT  
LABOR 1.5

#### Labor

| Job # | Description   | Hours | Total  |
|-------|---------------|-------|--------|
| 1     | REPAIRED AREA | 1.50  | 247.50 |

#### Other Services

| Code | Description            | Qty  | Price | Total |
|------|------------------------|------|-------|-------|
| SSE  | SHOP SUPPLIES EXTERNAL | 1.00 | 8.99  | 8.99  |
| NII  | W&R PAINT SUPPLY       | 1.00 | 34.45 | 34.45 |

**Subtotal for Job #1: 290.94**

### Job #2 - Warranty

COMPLAINT: ON DRIVER SIDE SLIDEOUT UNIT HAS PAINT ISSUES IN ONE AREA

CAUSE: NOTED ON DAF

CORRECTION: AREA NEEDS TO BE CLEANED, SAND AND REPAINT AREA  
LABOR 1.3

#### Labor

| Job # | Description   | Hours | Total |
|-------|---------------|-------|-------|
| 2     | REPAIRED AREA | 0.50  | 82.50 |

**Subtotal for Job #2: 82.50**

### Job #3 - Warranty

COMPLAINT: TRIM ON LIVING AREA SLIDE NEEDS FILLED IN, LOOKS DAMAGED WHEN YOU WALK IN THE COACH. THIS IS TWO DIFFERENT PLACES.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



**Labor**

| Job # | Description    | Hours | Total |
|-------|----------------|-------|-------|
| 3     | COLOR AND FILL | 0.20  | 33.00 |

**Subtotal for Job #3: 33.00****Job #4 - Warranty**

COMPLAINT: BATHROOM SINK COUNTER LOOKS DAMAGED FROM STAPLE/NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .30

**Labor**

| Job # | Description    | Hours | Total |
|-------|----------------|-------|-------|
| 4     | FILL AND COLOR | 0.50  | 82.50 |

**Subtotal for Job #4: 82.50****Job #5 - Warranty**

COMPLAINT: BATHROOM DOOR SCRATCHED IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .30

**Labor**

| Job # | Description | Hours | Total |
|-------|-------------|-------|-------|
| 5     | REPAIR      | 0.20  | 33.00 |

**Subtotal for Job #5: 33.00****Job #6 - Warranty**

COMPLAINT: STOVE GLASS COVER IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE GLASS STOVE TOP COVER

LABOR .50

**Labor**

| Job # | Description | Hours | Total |
|-------|-------------|-------|-------|
| 6     | REPAIR      | 0.25  | 41.25 |

**Subtotal for Job #6: 41.25**

Parts Total: 0.00  
Labour Total: 519.75  
Sublet Total: 0.00  
Extras Total: 43.44

**WORK ORDER TOTAL: 563.19**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY &amp; COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Customer Signature : \_\_\_\_\_

Date: 21 Nov 2025

W/O: 26353



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Customer Work  
Order

