



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26437
Promised Date:
26 DEC 25



WO #: 26437 (Appointment Date: 08 DEC 2025 - Time: 10:00am)

Customer: 93256 - REDDIN, MICHAEL
Address: 203 MIKES AVE
GREENEVILLE, TN
37745

Home Phone:
Work Phone:
Author: SPD
Location: IH
Invoice #: 422223

Stock #: 11053
Stock Desc: (11053) 2025 KZ-RV CONNECT
262RLK
Model: 262RLK
Serial #: 4EZTL2827S4097049
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 20 SEP 25
Date In: 29 NOV 25
Promise Date: 30 DEC 25
Promise Time: 09:00am
Schedule Date:
Completed: 25 FEB 26
Warr. Date: 20 SEP 25

Job #1 - Warranty

COMPLAINT: CS THAT THE SHOWER DOORS POPPED OF TRACK AND HIT THE WALL WHEN IN TRAVEL

CAUSE: SCREWS THAT HOLD ROLLERS WORKED LOOSE AND ALLOWED DOOR TO COME OUT OF THE TRACK AND DAMAGED WALL.

CORRECTION: REINSTALL ALL DOORS TO THE SHOWER, TIGHTEN ALL SCREWS TO ROLLERS ON BOTTOM OF SHOWER DOORS(4 ROLLERS). REMOVE AND REPLACE THE WALL PANELING NEXT TO THE BATHROOM SINK. TO REPLACE WALL PANEL WE NEED TO REMOVE AND REINSTALL OUTLET, TANKLESS CONTROL, DOOR FACING MEDICINE CABINET AND SINK CABINET PLUS ALL PLUMBING
LABOR 4.0

Labor

Job #	Description	Hours	Total
1	REPAIRED AREA	4.00	700.00

Parts

Part #	Description	Qty	Price	Total
161956	PANEL, HIGHLAND COVE EMPRESS, 3.6MMX48X96, 4 STAR	1.00	90.69	90.69

Other Services

Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	50.00	50.00
FRT	FREIGHT ON PARTS	1.00	233.00	233.00

Subtotal for Job #1: 1,073.69

Job #2 - Warranty

COMPLAINT: CS THAT THE FURNACE WILL KICKS ON BUT NO HEAT THEN SHUTS OFF

CAUSE: THERMOSTAT WAS DROPPING SIGNAL, PULLED FURNACE AND BENCH TESTED TO FURNACE. FAULTY T-STAT

CORRECTION: REPLACE T-STAT AND TEST
LABOR .50

Labor

Job #	Description	Hours	Total
2	REPLACED T-STAT AND TESTED	0.50	87.50

Parts

Customer #: 93256
REDDIN, MICHAEL



Part #	Description	Qty	Price	Total
164479	THERMOSTAT,A/C,COOL ONLY,BLACK,DIGITAL,HEAT-COOL,HE AT PUMP	1.00	63.18	63.18

Subtotal for Job #2: 150.68

Job #WINT2 - External
WINTERIZE-TT/CLASS C

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____


Labor				
Job #	Description	Hours		Total
WINT2	WINTERIZE FRESH WATER SYSTEM	0.00		N/C
Parts				
Part #	Description	Qty	Price	Total
56-1690	30A BLADE FUSE	1.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #WINT2:				0.00

Parts Total:	153.87
Labour Total:	787.50
Sublet Total:	0.00
Extras Total:	283.00
WORK ORDER TOTAL:	1,224.37

 I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
 X _____

 MOTOR VEHICLE REPAIR REGISTRATION #MV-04967
 Customer Signature : _____ Date: 25 Feb 2026

W/O: 26437
 Promised Date: 30 DEC 25



Customer #: 93256
 REDDIN, MICHAEL

