



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26446



WO #: 26446

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11247

Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2

Model: 351G2

Serial #: 4X4FVGL29T5404031

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 02 DEC 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 20 MAR 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: LINO FLOOR IS ROLLED UP IN THE BASEMENT AREA

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE PLASTIC TRAY AND SMOOTH OUT THE LINO FLOORING

LABOR .80

Labor

Job #	Description	Hours	Total
1	REPAIRED	1.00	175.00
Subtotal for Job #1:			175.00

Job #2 - Warranty

COMPLAINT: SEALANT HAS A HOLE ON THE LED STRIP ON FRONT CAP

CAUSE: NOTED ON DAF

CORRECTION: RESEAL AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	RESEALED AREA	0.20	35.00
Subtotal for Job #2:			35.00

Job #3 - Warranty

COMPLAINT: SHELF IN BEDROOM CLOSET IS STICKING UP ON ONE SIDE

CAUSE: NOTED ON DAF

CORRECTION: RESECURE SHELF IN CORRECT PLACE TO LAY FLAT

LABOR .20

Labor

Job #	Description	Hours	Total
3	RESECURED IN PLACE	0.20	35.00

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #3: 35.00

Job #4 - Warranty

COMPLAINT: CARPET STICKING OUT ON BOTH SIDES OF THE BEDROOM SLIDE

CAUSE: NOTED ON DAF

CORRECTION: CUT CARPET TO FIT CORRECTLY AND NOT STICK OUT

LABOR .50

Labor

Job #	Description	Hours	Total
4	REPAIRED	0.20	35.00

Subtotal for Job #4: 35.00

Job #5 - Warranty

COMPLAINT: THE PLASTIC TRIM ON THE POCKET DOOR GOING TO THE BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE PLASTIC TRIM GOING INTO BEDROOM

LABOR 1.0

Labor

Job #	Description	Hours	Total
5	REPLACED	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
30178736A	INTERIOR MOLDING U CHANNEL 2 7/8 X 8 BLACK	1.00	4.25	4.25

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	192.22	192.22

Subtotal for Job #5: 231.47

Job #6 - Warranty

COMPLAINT: GLASS DOOR GOING INTO THE PATIO AREA IS HARD TO OPEN AND CLOSE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST DOOR TO OPERATE CORRECTLY

LABOR .50

Labor

Job #	Description	Hours	Total
6	ADJUSTED DOOR	0.50	87.50

Subtotal for Job #6: 87.50

Job #7 - Warranty

COMPLAINT: BACK OF FOUR GLASS CABINET DOORS ARE GOUGED IN THE LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE GLASS ON ALL 4 CABINET DOORS IN LIVING AREA

LABOR 2.0

Labor

Job #	Description	Hours	Total
7	TOUCH UP	0.30	52.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #7: 52.50

Job #8 - Warranty

COMPLAINT: THE WIRE MESH ABOVE THE STOVE IS CUT WRONG AND BOWING OUT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE WIRE MESH AND CUT TO FIT THEN REINSTALL

LABOR .50

Labor

Job #	Description	Hours	Total
8	REPAIRED	0.20	35.00

Subtotal for Job #8: 35.00

Job #9 - Warranty

COMPLAINT: KITCHEN SINK IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SINK FROM COUNTER THAT IS GLUED DOWN,REMOVE ALL WATER CONNECTIONS AND DRAIN PIPE,CLEAN COUNTER. INSTALL NEW SINK, CONNECT ALL WATER CONNECTIONS AND DRAIN PIPE THEN TEST
LABOR 3.0**Labor**

Job #	Description	Hours	Total
9	BUFF AREA	0.50	87.50

Subtotal for Job #9: 87.50

Job #10 - Warranty

COMPLAINT: MARKS ON THE DOOR LATCH GOING OUT TO THE RAMP AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DOOR LATCH

LABOR .50

Labor

Job #	Description	Hours	Total
10	REPALCE LATCH	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100190107	DOOR HANDLE	1.00	149.25	149.25

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	5.00	5.00

Subtotal for Job #10: 189.25

Parts Total:	153.50
Labour Total:	612.50
Sublet Total:	0.00
Extras Total:	197.22

WORK ORDER TOTAL: 963.22Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 26446

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 20 Mar 2026

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

