



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26500
 Promised Date: 03 DEC 25



WO #: 26500 (Appointment Date: 03 DEC 2025 - Time: 10:00am)

Customer: 68842 - MORROW, MIKE
 Address: 1704 COOKS VALLEY ROAD
 KINGSPOUR, TN
 37664

Home Phone: 423-292-3906

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 2025 TT FOREST RIVER NOBO
 Stock Desc: NBT19.4
 Model: NBT19.4
 Serial #: 5NHTRDU19SD210599
 Chassis #:
 Mileage: 0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 03 DEC 25
 Promise Date: 30 DEC 25
 Promise Time: 09:00am
 Schedule Date:
 Completed: 28 FEB 26
 Warr. Date:

Job #1 - External

DOP: JULY 8, 2025

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: WOOD TRIM IN KITCHEN COMING OFF ON THE DOORS ABOVE THE SINK

CAUSE: DECORATIVE TAPE IS PEELING OFF THE CABINET DOORS AND ROLLING UP

CORRECTION: REPLACE BOTH CABINET DOOR DOORS
 LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED CABINET DOORS	3.20	528.00

Other Services

Code	Description	Qty	Price	Total
NII	F100683585	2.00	5.89	11.78
NII	F100683640	3.00	2.93	8.79
NII	F100683569	2.00	6.47	12.94
NII	F100683559	1.00	4.11	4.11

Subtotal for Job #2: 565.62

Job #3 - Warranty

TANK LEVEL GAGE IS NOT TELLING CUSTOMER WHEN THE TANKS ARE FULL PANEL IS SHOWING EMPTY CHECK BLACK TANK AND GRAY TANK

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CHECK LIGHT SWITCH ON MAIN PANEL
 CUST HAVING ISSUES WITH THE OUTSIDE FRONT LIGHTS SWITCH FEELS LIKE ITS STICKING

CAUSE: TECH VERIFIED THE PORCH LIGHT SWITCH IS VERY HARD TO OPERATE, FAULTY SWITCH

Customer #: 68842
 MORROW, MIKE



CORRECTION: REPLACE THE PORCH LIGHT SWITCH AND TEST
LABOR .30

Labor

Job #	Description	Hours	Total
4	REPLACED PORCH LIGHT SWITCH	0.10	16.50

Parts

Part #	Description	Qty	Price	Total
F100499011	1G INTERIOR LIGHT SWITCH	1.00	0.20	0.20

Subtotal for Job #4: 16.70

Job #5 - Warranty

COMPLAINT: LOCK IS STICKING ON STORAGE COMPARTMENT, PASSENGER SIDE CHECK ALL COMPARTMENT LOCKS

CAUSE: DS COMPARTMENT DOOR LOCK WILL NOT ALLOW TECH TO LOCK/UNLOCK LATCH

CORRECTION: REPLACE THE COMPLETE COMPARTMENT DOOR SLAM LATCH

LABOR .20

Labor

Job #	Description	Hours	Total
5	REPLACED SLAM LATCH	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
F100650216	SLAM LATCH	1.00	33.25	33.25

Subtotal for Job #5: 66.25

Job #6 - Warranty

COMPLAINT: WHEN CUSTOMER WAS TURNING HIS WATER HEATER BYPASS ON HE NOTICED A LEAK COMING FROM THAT AREA

CAUSE: VERIFIED THAT BOTH BYPASS/VALVE KNOBS ARE LEAKING

CORRECTION: REPLACE BOTH BYPASS VALVES AND TEST

LABOR 1.0

Labor

Job #	Description	Hours	Total
6	REPLACED VALVE	0.75	123.75

Parts

Part #	Description	Qty	Price	Total
F100040650	KIT, BY-PASS KIT, 14080: VALVE - WATER HEATER - 6 GAL - W/ SWIVEL ELBOWS	1.00	16.20	16.20
4678	1/2" PEX CLAMP	2.00	0.25	0.50

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	19.49	19.49

Subtotal for Job #6: 159.94

Job #7 - Warranty

COMPLAINT: CS THAT THE FRESH AIR INLET PANEL ON THE FURNACE HAS SCREWS THAT KEEP COMING LOOSE

CAUSE: SCREWS WILL NOT HOLD THE GRILL/COVER IN DESIGNED PLACE CORRECTLY.

CORRECTION: NEED TO REPLACE THE CURRENT SCREWS WITH LARGER SCREWS

LABOR .10

W/O: 26500
Promised Date: 30 DEC 25



Customer #: 68842
MORROW, MIKE



W/O: 26500
Promised Date: 30 DEC 25



Customer #: 68842
MORROW, MIKE



Labor				
Job #	Description		Hours	Total
7	REPLACED SCREW		0.20	33.00

Other Services				
Code	Description	Qty	Price	Total
NII	shop supply	1.00	5.99	5.99
Subtotal for Job #7:				38.99

Job #8 - Warranty

COMPLAINT: FRONT CAP LIGHT SWITCH IS COMING OUT OF PANEL

CAUSE: LIGHT SWITCH IS STICKING OUT ON THE PANEL.

CORRECTION: REMOVE PANEL, ADJUST WIRES GOING TO THE SWITCH AND RESECURE IN CORRECT PLACE
LABOR .50

Labor				
Job #	Description		Hours	Total
8	REPLACED PANEL		0.30	49.50

Parts				
Part #	Description	Qty	Price	Total
F100638596	SWITCH PLATE	1.00	46.01	46.01

Other Services				
Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	19.46	19.46
Subtotal for Job #8:				114.97

Parts Total:	96.16
Labour Total:	783.75
Sublet Total:	0.00
Extras Total:	82.56
WORK ORDER TOTAL:	962.47

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 Feb 2026

