



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26500
Promised Date: 03 DEC 25



WO #: 26500 (Appointment Date: 03 DEC 2025 - Time: 10:00am)

Customer: 68842 - MORROW, MIKE
Address: 1704 COOKS VALLEY ROAD
KINGSPORT, TN
37664

Home Phone: 423-292-3906

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 2025 TT FOREST RIVER NOBO
Stock Desc: NBT19.4
Model: NBT19.4
Serial #: 5NHTRDU19SD210599
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 03 DEC 25
Promise Date: 30 DEC 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

DOP: JULY 8, 2025

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: WOOD TRIM IN KITCHEN COMING OFF ON THE DOORS ABOVE THE SINK

CAUSE: DECORATIVE TAPE IS PEELING OFF THE CABINET DOORS AND ROLLING UP

CORRECTION: REPLACE BOTH CABINET DOOR DOORS
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

TANK LEVEL GAGE IS NOT TELLING CUSTOMER WHEN THE TANKS ARE FULL PANEL IS SHOWING EMPTY CHECK BLACK TANK AND GRAY TANK

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CHECK LIGHT SWITCH ON MAIN PANEL
CUST HAVING ISSUES WITH THE OUTSIDE FRONT LIGHTS SWITCH FEELS LIKE ITS STICKING

CAUSE: TECH VERIFIED THE PORCH LIGHT SWITCH IS VERY HARD TO OPERATE, FAULTY SWITCH

CORRECTION: REPLACE THE PORCH LIGHT SWITCH AND TEST
LABOR .30

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: LOCK IS STICKING ON STORAGE COMPARTMENT, PASSENGER SIDE CHECK ALL COMPARTMENT LOCKS

CAUSE: DS COMPARTMENT DOOR LOCK WILL NOT ALLOW TECH TO LOCK/UNLOCK LATCH

Customer #: 68842
MORROW, MIKE



CORRECTION: REPLACE THE COMPLETE COMPARTMENT DOOR SLAM LATCH
LABOR .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: WHEN CUSTOMER WAS TURNING HIS WATER HEATER BYPASS ON HE NOTICED A
LEAK COMING FROM THAT AREA

CAUSE: VERIFIED THAT BOTH BYPASS/VALVE KNOBS ARE LEAKING

CORRECTION: REPLACE BOTH BYPASS VALVES AND TEST
LABOR 1.0

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CS THAT THE FRESH AIR INLET PANEL ON THE FURNACE HAS SCREWS THAT KEEP
COMING LOOSE

CAUSE: SCREWS WILL NOT HOLD THE GRILL/COVER IN DESIGNED PLACE CORRECTLY.

CORRECTION: NEED TO REPLACE THE CURRENT SCREWS WITH LARGER SCREWS
LABOR .10

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: FRONT CAP LIGHT SWITCH IS COMING OUT OF PANEL

CAUSE: LIGHT SWITCH IS STICKING OUT ON THE PANEL.

CORRECTION: REMOVE PANEL, ADJUST WIRES GOING TO THE SWITCH AND RESECURE IN
CORRECT PLACE
LABOR .50

Subtotal for Job #8: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X_____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 09 Jan 2026

W/O: 26500
Promised Date: 30 DEC 25



Customer #: 68842
MORROW, MIKE

