



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26576



WO #: 26576 (Appointment Date: 22 DEC 2025 - Time: 09:00am)

Customer: 82920 - MCMACKIN, TERRY  
 Address: 116 DUCKTOWN RD  
 LIMESTONE, TN  
 37681

Home Phone: 423-426-3230

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11044

Stock Desc: (11044) 2025 FOREST RIVER

SANDPIPER 4003MB

Model: 4003MB

Serial #: 4X4FSAS2XSJ047682

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 12 MAY 25

Date In: 22 DEC 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 09 MAR 26

Warr. Date: 12 MAY 25

**Job #1 - Warranty**

COMPLAINT: WATER HAS LEAKED INTO THE HALLWAY AND HAS CAUSED THE TRIM AND DOOR FRAME TO SWELL CHECK AND ADVISE bathroom door, bedroom door and vanity

CAUSE: SHOWER SEALS HAVE FAILED AND ALLOWED WATER TO LEAK AND DAMAGED THE STILE.

STILE AROUND BATHROOM AND BEDROOM DOOR ARE DAMAGED.

CORRECTION: RESEAL SHOWER

REPLACE THE DOOR STILE ON BEDROOM AND BATHROOM DOOR

LABOR 2.0

**Labor**

Job #	Description	Hours	Total
1	REPLACED TRIM	2.00	350.00

**Parts**

Part #	Description	Qty	Price	Total
F100635860	DOOR CASING, 1 1/4" X 3.42" X 97" FRINTON SAND (41204) 2025- / 47090414	2.00	19.37	38.74
F100649641	STILE	1.00	11.39	11.39

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	5.99	5.99
FRT	FREIGHT ON PARTS	1.00	124.17	124.17

**Subtotal for Job #1: 530.29**

**Job #ROOFINS - External**

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING\_\_\_\_\_

CHECK SKYLIGHTS\_\_\_\_\_

CHECK ROOF VENTS\_\_\_\_\_

CHECK LUBE & ANTENNA\_\_\_\_\_

CHECK SATELLITE\_\_\_\_\_

CHECK RUBBER\_\_\_\_\_

CORRECTION: ROOF LOOKS GOOD AT THIS TIME

RECHECK IN 6 MONTHS

Customer #: 82920  
 MCMACKIN, TERRY



Subtotal for Job #ROOFINS: 0.00

**Job #3 - External**

COMPLAINT: check left side of basement water was standing on the left side

CORRECTION: ALL IS GOOD AT THIS TIME

Subtotal for Job #3: 0.00

**Job #4 - Warranty**

COMPLAINT: FRIDGE DOOR IS HITTING THE KNOB ON BUNK HOUSE DOOR

CORRECTION: FRIDGE WAS SET BACK TO ALLOW THE DOOR TO NOT HIT

Subtotal for Job #4: 0.00

Parts Total:	50.13
Labour Total:	350.00
Sublet Total:	0.00
Extras Total:	130.16
<b>WORK ORDER TOTAL:</b>	<b>530.29</b>

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 09 Mar 2026

W/O: 26576



Customer #: 82920  
MCMACKIN, TERRY

