



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26576



WO #: 26576 (Appointment Date: 22 DEC 2025 - Time: 09:00am)

Customer: 82920 - MCMACKIN, TERRY
 Address: 116 DUCKTOWN RD
 LIMESTONE, TN
 37681

Home Phone: 423-426-3230

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 11044

Stock Desc: (11044) 2025 FOREST RIVER

SANDPIPER 4003MB

Model: 4003MB

Serial #: 4X4FSAS2XSJ047682

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 12 MAY 25

Date In: 22 DEC 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 12 MAY 25

Job #1 - External

COMPLAINT: WATER HAS LEAKED INTO THE HALLWAY AND HAS CAUSED THE TRIM AND DOOR FRAME TO SWELL CHECK AND ADVISE bathroom door, bedroom door and vanity

CAUSE: SHOWER SEALS HAVE FAILED AND ALLOWED WATER TO LEAK AND DAMAGED THE STILE.

STILE AROUND BATHROOM AND BEDROOM DOOR ARE DAMAGED.

CORRECTION: RESEAL SHOWER

REPLACE THE DOOR STILE ON BEDROOM AND BATHROOM DOOR

LABOR 2.5

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING_____

CHECK SKYLIGHTS_____

CHECK ROOF VENTS_____

CHECK LUBE & ANTENNA_____

CHECK SATELLITE_____

CHECK RUBBER_____

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

check left side of basement water was standing on the left side

Subtotal for Job #3: 0.00

Job #4 - Warranty

FRIDGE DOOR IS HITTING THE KNOB ON BUNK HOUSE DOOR

Subtotal for Job #4: 0.00

Customer #: 82920
 MCMACKIN, TERRY



W/O: 26576

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 19 Jan 2026

Customer Signature : _____

Customer Work Order



Customer #: 82920
MCMACKIN, TERRY

