



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26581



WO #: 26581

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11251

Stock Desc: 2026 FW FOREST RIVER

SANDPIPER 3844QUAD

Model: 3844QUAD

Serial #: 4X4FSAP21TJ049010

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 23 DEC 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: DOOR SIDE REAR COMPARTMENT DOOR IS NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF

COMPARTMENT DOOR IS HITTING THE SIDE OF THE OPENING ON THE UNIT WHEN YOU CLOSE IT

CORRECTION: ADJUST COMPARTMENT DOOR

LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LIGHT OVER THE ENTRY DOOR IS NOT STRAIGHT

CAUSE: NOTED ON DAF

CORRECTION: RESECURE LIGHT IN PROPERLY AND STRAIGHT THEN RESEAL AROUND LIGHT

LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THERE IS A PAINT CHIP ON THE FRONT CAP OF THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: AREA NEEDS TO BE CLEANED AND TAPED OFF, LIGHTLY SAND, PRIME, REPAINT

AFFECTED AREA TO MATCH UNIT. ALLOW PAINT TO CURE, THEN LIGHTLY BUFF AND POLISH

LABOR 3.5

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DRAWER IN BEDROOM IS SPLITTING ON THE SIDE AND HAS A CHIP

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DRAWER WITH NEW ONE

REMOVE AND REINSTALL DRAWER GUIDES ON BOTH SIDES

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: THE 2ND DRAWER DOWN IN THE BEDROOM WILL NOT CLOSE

CAUSE: NOTED ON DAF
DRAWER GUIDES ARE FAULTY

CORRECTION: REPLACE DRAWERS GUIDES
LABOR .30

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: INTERIOR DOOR TRIM IS DAMAGED. TRIM IS BUBBLING UP IN PLACES AND HAS HOLES ACROSS IT THAT ARE DEEP

CAUSE: NOTED ON DAF
DAMAGED AT FACTORY INSTALL

CORRECTION: REMOVE CURRENT TRIM AND REPLACE WITH NEW, COLOR AND FILL IF NEEDED
LABOR .40

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: FASCIA IN THE BEDROOM IS SCRATCHED AT THE TOP

CAUSE: NOTED ON DAF
SCRATCHED AT INSTALL

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: LIVING AREA FASCIA HAS RED MARKS ACROSS THE TOP AND PLACES THAT ARE CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA THAT HAS THE RED SPOTS THEN FILL, COLOR AND BLEND AREA
LABOR .30

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: UNIT HAS MULTIPLE AREAS OF DULL PAINT FINISH THAT DOES NOT MATCH THE SURROUNDING PANELS.AFFECTED AREAS LACK PROPER GLOSS AND CLARITY COMPARED TO THE REST OF THE PAINT JOB.THESE AREAS ARE NDS MIDDLE OF UNIT, OVER REAR DOOR AREA AND AT FRONT COMPARTMENT DOOR

CAUSE: PAINT FINISH INCONSISTENCY RESULTING IN DULL APPEARANCE AND GLOSS MISMATCH

CORRECTION: AREAS NEED TO BE REFINISHED, RESTORE PROPER GLOSS AND ENSURE PAINT FINISH MATCHES PANELS.
LABOR 4.5

W/O: 26581



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #9: 0.00

W/O: 26581

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 23 Dec 2025



Customer Work Order

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

