



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26610



WO #: 26610

Customer: 76267 - NEUBRANDER, JOHANNA
Address: 215 SWANAY RD
CHUCKEY, TN
37641

Home Phone: 423-737-6856

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11081

Stock Desc: 2025 FW DUTCHMEN ASTORIA
260RK

Model: 260RK

Serial #: 4YDFAAM26SZ915553

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 18 JUL 25

Date In: 07 JAN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 18 JUL 25

Job #1 - Warranty

COMPLAINT: SHOWER DOOR HANDLE HAS CAME OFF

CAUSE: SHOWER DOOR END HANDLE CAME OFF AND THE OTHER SIDE CAME LOOSE

CORRECTION: RESECURE HANDLE IN CORRECT PLACE

LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: DRIVER SIDE SMALL COMPARTMENT DOOR LOCK JUST SPINS

CAUSE: THE SCREW THAT SECURES LATCH IN PLACE CAME LOOSE CAUSING LOCK TO TURN

CORRECTION: LINE LOCK INTO PROPER POSITION THEN RESECURE SCREW

LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: LEFT RECLINER FOOT REST IS COMING OUT WHEN JUST SITTING IN IT AND MAKE ANY MOVEMENT. CUST ALSO STATED THE FOOT REST WILL GO OUT WHILE THEY ARE TRAVELING. RIGHT SIDE WILL NOT COME OUT AT ALL

CAUSE: TECH VERIFIED THE RIGHT RECLINER WILL NOT OPEN WITHOUT EXTREME FORCE. LEFT SODE WILL NOT LATCH TO KEEP THE FOOT REST IN AS DESIGNED. BOTH RECLINERS HAVE INTERNAL ISSUES THAT ARE NOT ALLOWING THE CUSTOMER TO USE THEM CORRECTLY.

CORRECTION: REPLACE THE LEFT AND RIGHT SIDE OF THE RECLINERS

LABOR 2.0

Subtotal for Job #3: 0.00

Customer #: 76267
NEUBRANDER, JOHANNA



W/O: 26610

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 08 Jan 2026

Customer Signature : _____

Customer Work Order



Customer #: 76267
NEUBRANDER, JOHANNA

