



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26641
Promised Date:
26 JAN 26



WO #: 26641

Customer: 92565 - CAMPBELL, BRET
Address: 156 LINK RD
COTTONTOWN, TN
37048

Home Phone: (615) 983-9354

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 10992

Stock Desc: 2025 TT FOREST RIVER

ROCKWOOD MINI 2513S

Model: 2513S

Serial #: 4X4TRLB2XSD461344

Chassis #:

Mileage: 0

Key #: 4500

Req'n #:

License #:

Trim:

Purchase Date: 07 MAR 25

Date In: 16 JAN 26

Promise Date: 30 JAN 26

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 07 MAR 25

Job #1 - Warranty

COMPLAINT: WATER LEAKING UNDERNEATH LIVING ROOM SLIDE

CORRECTION: NO ISSUES AT THIS TIME

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE CLIP FOR THE SHOWER DOOR NOT LATCHING EASILY

CAUSE: LATCH CRACKED AND WILL NOT WORK AS DESIGNED (CJS)

CORRECTION: REPLACE LATCH ON SHOWER DOOR
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

PANEL IS PULLING AWAY AROUND KITCH COUNTER CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DRAWER NOT LATCHING CLOSED IN KITCHEN

CAUSE: DRAWER WAS INSTALLED CROOKED CASUING THE GUIDE TO GET DAMAGED.(CJS)

CORRECTION: REMOVE DRAWER AND GUIDES, REPLACE GUIDES WITH NEW ONES AND
REINSTALL DRAWER
LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BURNER STOVE OUTSIDE IS NOT EASILY LIGHTING FROM BENT BURNER ASSEMBLY

CAUSE: BURNER IS BENT (CJS)

CORRECTION: REPLACE BURNER AND TEST
LABOR 1.0

Customer #: 92565
CAMPBELL, BRET



W/O: 26641
Promised Date: 30 JAN 26



Customer #: 92565
CAMPBELL, BRET



Subtotal for Job #5: 0.00

Job #6 - External

CUSTOMER STATES UNIT IS WINTERIZED

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: DOORSIDE PASSTHROUGH COMPARTMENT LOCK IS STICKING CHECK AND ADVISE (CHECK ALL OF THE LOCKS)

CAUSE: COMPARTMENT DOOR IS OUT OF ADJUSTMENT (CJS)

CORRECTION: ADJUST COMPARTMENT DOOR
LABOR .30

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: MAIN AWNING IS SHOOTING WATER INTO PASSTHROUGH BAGGAGE DOOR ON DOOR SIDE FRONT CHECK AND ADVISE

CORRECTION: NO ISSUES FOUND

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: OUTSIDE KITCHEN BAGGAGE DOOR IS PULLING AWAY FROM HINGES

CAUSE: RIVITS ARE FAULTY ON DOOR AND PULLING LOOSE FROM COMPARTMENT DOOR. THIS IS NOT ALLOWING THE DOOR TO CLOSE CORRECTLY AND COULD ALLOW WATER IN AREA

CORRECTION: REMOVE AND REPLACE THE COMPARTMENT DOOR
RESEAL AREA
LABOR 1.0

Subtotal for Job #9: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 Feb 2026

