



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26698



WO #: 26698

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11268

Stock Desc: 2026 TT KZ-RV SPORTSMEN SE

292RBKSE

Model: 292RBKSE

Serial #: 4EZTU3025T5010694

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 09 FEB 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 18 MAR 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: SCREW BROKE OFF IN SCREEN DOOR

CAUSE: SCREW BROKE OFF IN SCREEN DOOR
NOTED ON DAF

CORRECTION: REPLACE SCREEN DOOR
LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED SCREEN DOOR	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
505219	DOOR, SCREEN, 26X72, 8000 R 26 X 72 RH STDSCDBK BKP STD LATCH (FOR 161128)	1.00	163.80	163.80

Other Services

Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	50.00	50.00
FRT	FREIGHT ON PARTS	1.00	17.03	17.03

Subtotal for Job #1: 265.83

Job #2 - Warranty

COMPLAINT: BATHROOM MED CABINET HAS CHIPS ON CORNER, THIS IS IN TWO DIFF PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND BOTH AREAS
LABOR .30

Labor

Job #	Description	Hours	Total
2	FILLED AND COLORED	0.10	17.50

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	5.99	5.99

Subtotal for Job #2: 23.49

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Job #3 - Warranty

COMPLAINT: SEVERAL SPOTS ON SLIDE OUT FASCIA HAS HOLES AND PLACES PEELING BACK

CAUSE: DAMAGED AT BUILD
NOTED ON DAFCORRECTION: FILL COLOR AND BLEND AREAS
LABOR .30**Labor**

Job #	Description	Hours	Total
3	FILLED AND COLORED	0.30	52.50
Subtotal for Job #3:			52.50

Job #4 - Warranty

COMPLAINT: AWNING WILL NOT RETRACT IN AFTER IT WAS EXTENDED

CAUSE: AWNING SWITCH ON PANEL IS FAULTY AND WILL NOT WORK TO RETRACT AWNING
BACK IN
NOTED ON DAFCORRECTION: REPLACE SWITCH AND TEST
LABOR .50**Labor**

Job #	Description	Hours	Total
4	REPLACED SWITCH	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
164488	SWITCH,SLIDEOUT,4 TERMINAL,POLARITY REVERSING,(REPLACED 154132)	1.00	17.55	17.55

Subtotal for Job #4: 70.05

Job #5 - WarrantyCOMPLAINT: BEDROOM CLOSET DOOR HAS A PLACE RUBBED OFF ON WALL INSIDE AND PANEL
ON CLOSET FLOORING IS LOOSE AND NOT SECURED IN CORRECTLY

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA
PANEL ON BOTTOM OF CLOSET NEEDS RESECURED AND FILLED TO NOT LOOK LIKE A CRACK
ON THE SIDE AT WALL
LABOR .50**Labor**

Job #	Description	Hours	Total
5	COLOR AND BLEND AREA	0.30	52.50
Subtotal for Job #5:			52.50

Job #6 - Warranty

COMPLAINT: BEDROOM DOOR HAS A CHIPPED SPOT

CAUSE: NOTED ON DAF

CORRECTION: COLOR FILL AND BLEND AREA
LABOR .20Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Labor

Job #	Description	Hours	Total
6	COLOR AND FILL	0.20	35.00
Subtotal for Job #6:			35.00

W/O: 26698

Parts Total: 181.35
Labour Total: 245.00
Sublet Total: 0.00
Extras Total: 73.02
WORK ORDER TOTAL: 499.37

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 18 Mar 2026



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

