



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26700



WO #: 26700

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11262

Stock Desc: 2026 TT KZ-RV SPORTSMEN SEL
241BHSL

Model: 241BHSL

Serial #: 4EZTU2525T5010908

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 09 FEB 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 24 FEB 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: GUTTER RAIL AT ENTRY DOOR NOT SEALED, WATER IS LEAKING INTO THE FRONT ENTRY DOOR

CAUSE: GUTTER RAIL NOT SEALED
NOTED ON DAF

CORRECTION: SEAL AREA AND TEST
LABOR .40

Labor

Job #	Description	Hours	Total
1	SEALED AND TEST	0.40	70.00

Parts

Part #	Description	Qty	Price	Total
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	11.86	11.86

Subtotal for Job #1: 81.86

Job #2 - Warranty

COMPLAINT: KITCHEN SHADE ABOVE COUNTER AT STOVE WILL NOT STAY UP

CAUSE: NOTED ON DAF

CORRECTION: REMOVE VALANCE TO ACCESS SHADE, REMOVE SHADE, ADJUST AND REINSTALL
LABOR .50

Labor

Job #	Description	Hours	Total
2	ADJ SHADE	0.10	17.50

Subtotal for Job #2: 17.50

Job #3 - Warranty

COMPLAINT: CHIP IN BATHROOM CABINET DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA
LABOR .30

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
3	FILL AND COLOR	0.20	35.00
Subtotal for Job #3:			35.00

Job #4 - Warranty

COMPLAINT: CHIP IN THE STILE AROUND THE BATHROOM MIRROR

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA

LABOR .30

Labor			
Job #	Description	Hours	Total
4	FILL AND COLOR	0.20	35.00
Subtotal for Job #4:			35.00

Job #5 - Warranty

COMPLAINT: STILE ON SLIDE OUT HAS SEVERAL HOLES AND SMALL CHIPS

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA

LABOR .30

Labor			
Job #	Description	Hours	Total
5	FILL AND COLOR	0.20	35.00
Subtotal for Job #5:			35.00

Job #6 - Warranty

COMPLAINT: STAINS ON THE WALL NEXT TO TV MANTEL IN LIVING ROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN BLACK SPOTS,COLOR MATCH AND BLEND AREAS

LABOR .50

Labor			
Job #	Description	Hours	Total
6	CLEAN AND COLOR MATCH	0.50	87.50
Subtotal for Job #6:			87.50

Job #7 - Warranty

COMPLAINT: STILE ON MANTEL IN LIVING ROOM IS BUSTED ON BOTTOM

CAUSE: NOTED ON DAF

CORRECTION: REMOVE BUSTED STILE AND REPLACE WITH NEW, BLEND COLOR IF NEEDED

LABOR 1.0

Labor			
Job #	Description	Hours	Total
7	FILL AND COLOR	0.20	35.00
Subtotal for Job #7:			35.00

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 26700

Parts Total:	11.86
Labour Total:	315.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	326.86

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 24 Feb 2026

Customer Signature : _____



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

