



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26739



WO #: 26739

Customer: 87620 - PARKER, ROBERT
Address: 1457 SCENIC DRIVE
NEW MARKET, TN
37820
Home Phone: (865) 850-3553
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11130
Stock Desc: 2025 FW DUTCHMEN ASTORIA
3173RLP
Model: 3173RLP
Serial #: 4YDFAAR27SZ915716
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 29 DEC 25
Date In: 18 FEB 26
Promise Date:
Promise Time:
Schedule Date:
Completed: 20 MAR 26
Warr. Date: 29 DEC 25

Job #1 - Warranty

COMPLAINT: LIC PLATE SCREW IS STRIPPED OUT AND WILL NOT HOLD TAG IN PLACE

CAUSE: SCREW HOLE STRIPPED ON LIC PLATE

CORRECTION: REPLACE LIC PLATE BRACKET
LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
557399	LICENSE PLATE BRACKET	1.00	5.27	5.27

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	15.50	15.50

Subtotal for Job #1: 55.77

Job #2 - Warranty

COMPLAINT: SCREW COVER AND THE CORNER CAP IS PEELING

CAUSE: THE PAINT IS COMING OFF THE CORNER CAP AND VINYL INSERT. THIS MAKES THE UNIT LOOK FADED AND DAMAGED ON THESE AREAS

CORRECTION: REPLACE BOTH REAR CORNER CAPS AND REPLACE THE VINYL INSERT RESEAL IF NEEDED
LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
533289	TRIM CORNER RADIUS	2.00	1.21	2.42
13-3077	DICOR 551LSB-1	1.00	8.92	8.92

Customer #: 87620
PARKER, ROBERT



Subtotal for Job #2: 273.84

W/O: 26739

Parts Total: 16.61
Labour Total: 297.50
Sublet Total: 0.00
Extras Total: 15.50

WORK ORDER TOTAL: 329.61

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Mar 2026



Customer #: 87620
PARKER, ROBERT



Customer Work Order

