



Pre-Authorization

Pre-Authorization number

PRAUTH74880
(PA03967061)

Reference no. 26739

Status

Approved

Servicing Dealer 8140

Name Tri-AM RV Center of East TN

Address 1202 Idell Rd
Bulls Gap, TN 37711

VIN 4YDFAAR27SZ915716

Retail sold on 12/22/2025

Root			Approved		Actual			
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	Base hours	Complaint/Cause/Correction
5101914B	Light, Clearance & Taillight - Replace	0	0.5	0.2		1	0.2	Complaint: *Do not know labor code, please advise. License plate screw is stripped out and will not hold tag in place Cause: Screw hole stripped on license plate Correction: Replace license plate bracket
2200106B	Corner Moldings - DS - Ft - Replace	0	1.5	1.5		1	0.5	Complaint: Screw cover and the corner cap is peeling Cause: The paint is coming off the corner cap and vinyl insert. This makes the unit look faded and damaged on these areas Correction: Replace both rear corner caps and replace the vinyl insert, reseal if needed
Pre-Authorization number: PRAUTH74880				1.7				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.