



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26770



WO #: 26770

Customer: 93683 - HART, CHRISTOPHER  
 Address: 990 SCENIC RIVER DR  
 ROCKY MOUNT, VA  
 24151  
 Home Phone: (540) 493-1198  
 Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11009  
 Stock Desc: 2025 CT FOREST RIVER  
 ROCKWOOD CAMP 2318FT  
 Model: 2318FT  
 Serial #: 4X4CFM715SD320860  
 Chassis #:  
 Mileage:  
 Key #: 1500  
 Req'n #:  
 License #:  
 Trim:

Purchase Date: 28 FEB 26  
 Date In: 26 FEB 26  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 18 MAR 26  
 Warr. Date: 28 FEB 26

**Job #1 - Warranty**

COMPLAINT: CABINET DOOR UNDER BENCH TO THE LEFT OF THE ENTRY DOOR IS PEELING AT ALL CORNERS

CAUSE: THE OVERLAY IS COMING OFF THE CABINET DOORS

CORRECTION: REPLACE CABINET DOOR  
 LABOR .20

**Labor**

Job #	Description	Hours	Total
1	REPLACED CABINET DOOR	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595218	CABINET DOOR 10X18	1.00	17.93	17.93

**Subtotal for Job #1: 87.93**

**Job #2 - Warranty**

COMPLAINT: CABINET DOOR UNDER BENCH #2 IS PEELING ON ALL CORNERS

CAUSE: OVERLAY ON CABINET DOOR IS PEELING OFF

CORRECTION: REPLACE CABINET DOOR  
 LABOR .20

**Labor**

Job #	Description	Hours	Total
2	REPLACED CABINET	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595218	CABINET DOOR 10X18	1.00	17.93	17.93

**Subtotal for Job #2: 87.93**

**Job #3 - Warranty**

COMPLAINT: FALSE CABINET DOOR UNDER SINK IS PEELING OFF ON CORNERS

CAUSE: OVERLAY ON CABINET IS PEELING OFF

CORRECTION: REPLACE CABINET DOOR

Customer #: 93683  
 HART, CHRISTOPHER



LABOR .20

**Labor**

Job #	Description	Hours	Total
3	REPLACED CABINET DOOR	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595217	CABINET 9X10	1.00	14.07	14.07

**Subtotal for Job #3: 84.07**

**Job #4 - Warranty**

COMPLAINT: SMALL CABINET DOOR BESIDE BED IS PEELING ON CORNERS

CAUSE: OVERLAY IS PEELING OFF THE CABINET

CORRECTION: REPLACE CABINET DOOR

LABOR .20

**Labor**

Job #	Description	Hours	Total
4	CABINET DOOR REPLACED	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595721	CABINET DOOR 6X9	1.00	12.77	12.77

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	19.51	19.51

**Subtotal for Job #4: 102.28**

**Job #5 - Warranty**

COMPLAINT: PRIVACY CURTAIN RACK CAME LOOSE FROM CEILING AND FELL FROM CEILING

CAUSE: SCREWS CAME LOOSE THAT HOLDS THE TRACK IN PLACE.

CORRECTION: RESECURE THE TRACK IN PLACE ON THE CEILING

LABOR .40

**Labor**

Job #	Description	Hours	Total
5	RESECURED TRACK IN PLACE	0.40	70.00

**Subtotal for Job #5: 70.00**

**Job #6 - Warranty**

COMPLAINT: CABINET DOOR ON LEFT OF SEATING AT ENTRY IS PEELING

CAUSE: OVERLAY IS PEELING OFF

CORRECTION: REPLACE CABINET DOOR

LABOR .20

**Labor**

Job #	Description	Hours	Total
6	REPLACED CABINET DOOR	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595720	CABINET DOOR - PFL: ANDOVER SABLE - 15 3/4" X 12 1/4" - V# 685502   X	1.00	18.41	18.41

W/O: 26770



Customer #: 93683  
HART, CHRISTOPHER



Subtotal for Job #6: 88.41

W/O: 26770

**Job #7 - Warranty**

COMPLAINT: CABINET DOOR TO THE RIGHT OF SEATING IS PEELING OFF

CAUSE: OVERLAY IS COMING OFF THE CABINET

CORRECTION: REPLACE CABINET DOOR  
LABOR .20

**Labor**

Job #	Description	Hours	Total
7	REPLACED CABINET DOOR	0.40	70.00

**Parts**

Part #	Description	Qty	Price	Total
F100595720	CABINET DOOR - PFL: ANDOVER SABLE - 15 3/4" X 12 1/4" - V# 685502   X	1.00	18.41	18.41

Subtotal for Job #7: 88.41

Parts Total: 99.52  
 Labour Total: 490.00  
 Sublet Total: 0.00  
 Extras Total: 19.51  
**WORK ORDER TOTAL: 609.03**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 18 Mar 2026



Customer #: 93683  
HART, CHRISTOPHER

