



Pre-Authorization

Pre-Authorization number

PREAUTH90446  
(PA03982068)

Reference no.26869

Status

Approved

Servicing Dealer 8140

Name Tri-AM RV Center of East TN

Address 1202 Idell Rd  
Bulls Gap, TN 37711

VIN 4YDTATG1XT8920098

Retail sold on 1/30/2026

| Root                                   |                                                 | Approved |           |       | Actual |     | Base  |                                                                                                                                                                                                                                                                                                                                                                |
|----------------------------------------|-------------------------------------------------|----------|-----------|-------|--------|-----|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Operation Description                  |                                                 | Sublet   | Sub Hours | Hours | hours  | Qty | hours | Complaint/Cause/Correction                                                                                                                                                                                                                                                                                                                                     |
| 4109708B                               | Cooktop - Atwood/Dometic - 0<br>All other parts |          | 0.5       | 0.5   |        | 1   | 0.5   | <b>Complaint:</b> Burner assembly on rear eye turns off after 20 seconds when something is over it (IE: a coffee pot)<br><b>Cause:</b> Tech verified the thermo coupler was bent up to the burner. This was causing the burner assembly to turn off<br><b>Correction:</b> Adjust the thermo coupler way from the burner and test<br><br>KRV-Approved to adjust |
| Pre-Authorization number: PREAUTH90446 |                                                 |          |           | 0.5   |        |     |       |                                                                                                                                                                                                                                                                                                                                                                |

For paper claims only use one pre-authorization number per warranty claim form.  
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.