



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26801
 Promised Date: 09 MAR 26



WO #: 26801 (Appointment Date: 09 MAR 2026 - Time: 10:00am)

Customer: 93045 - SWIFT, AUBURNI
 Address: 13525 HWY 67 WEST
 BUTLER, TN
 37640

Home Phone:
 Work Phone:
 Author: SPD
 Location: IH
 Invoice #:

Stock #: 11087
 Stock Desc: 2025 THTT FOREST RIVER ROGUE
 29SUT
 Model: 29SUT
 Serial #: 5NHTVGE28SC005513
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date: 19 JUL 25
 Date In: 07 MAR 26
 Promise Date: 30 MAR 26
 Promise Time: 09:00am
 Schedule Date:
 Completed: 13 APR 26
 Warr. Date: 19 JUL 25

Job #1 - Warranty

COMPLAINT: cs that the trim is coming loose ON OUTSIDE FRONT UNDER FRONT WINDOW

CAUSE: JWRAP ANCHOR RAIL SEPERATING FROM WALL

CORRECTION: NEED TO REMOVE THE JWRAP AND RESECURE RAIL AND REINSTALL JWRAP TO CORRECT DOOR
 LABOR .50

Labor

Job #	Description	Hours	Total
1	ADDED A SCEW A RESEAL	0.50	87.50
Subtotal for Job #1:			87.50

Job #2 - Warranty

COMPLAINT: CS THAT RAMP DOOR IS LEAKING OFF DOOR SIDE REAR

CAUSE: PREFORMED WATER TEST TO VERIFY WATER LEAK. WATER IS LEAKING PAST SEAL ON OFF DOOR SIDE OF RAMP.

CORRECTION: REMOVE CURRENT SEAL ON RAMP DOOR AND REPLACE WITH NEW SEAL , WATER TEST.
 LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED RAMP DOOR SEAL	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
F100694808	SEAL, 5/8" X 25FT SLIDE OUT LG BULB "D" SEAL SELF ADHESIVE - BLACK	1.00	40.76	40.76

Subtotal for Job #2: 215.76

Job #3 - Warranty

COMPLAINT: CS THAT THE AWNING LEAKS AT A SEAM ABOVE THE LIVING ROOM ENTRY DOOR

CAUSE: WATER IS LEAKING THROUGH SEAM WHERE AWNING RAIL/GUTTER MEET.

Customer #: 93045
 SWIFT, AUBURNI



CORRECTION: TECH REQUEST TO CLEAN AREA AND RESEAL TO STOP THE LEAKING LABOR .20

Labor			
Job #	Description	Hours	Total
3	CLEANED AND RESEAL	0.20	35.00
Subtotal for Job #3:			35.00

Job #4 - Warranty

COMPLAINT: CS THAT AWNING WONT ROLL OUT WITHOUT HELP ARMS ARE STICKING

CAUSE: TECH WAS ABLE TO EXTEND AND RETRACK THE AWNING AT THIS TIME WITH NO ISSUES (JPS)

WARRANTY VERIFIED THIS AWNING IS WORKING AS DESIGNED. (SPD)

CORRECTION: EMPLOYEE WILL GO OVER THIS WITH CUSTOMER AT PICK UP

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CS THAT THE FRONT COMPARTMENT DOOR WHERE GEN GOES IS LEAKING WATER IN

CAUSE: TECH VERIFIED THIS ISSUE BY PUTTING WATER ON THE AREA AND CONFIRMED THE LEAK INTO THE COMPARTMENT DOOR. WATER IS GETTING IN THROUGH SEAL BEING FAULTY.

CORRECTION: NEED TO REMOVE THE CURRENT SEAL AND REPLACE WITH NEW DOOR SEAL LABOR .50

Labor			
Job #	Description	Hours	Total
5	REPLACED SEAL AND TESTED	0.50	87.50

Parts				
Part #	Description	Qty	Price	Total
F100263737	ENTRY DOOR PART: RUBBER D-SEAL, .630"X .497" EPDM SPONGE MEDIUM DENSITY - BLACK, LIPPERT U17 SEAL RACK-SHELF 1	10.00	0.65	6.50

Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	26.42	26.42

Subtotal for Job #5: 120.42

Job #6 - Warranty

CS THAT THE CAMERA IS INOP CANT LINK TO PHONE NO SCREEN WITH UNIT

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CS THAT WATER IN THE SHOWER WILL NOT STAY HOT UNLESS YOU RUN THE WATER IN THE BATHROOM SINK

CAUSE: TECH WAS NOT TO DUPLICATE CONCERN AT THIS TIME. WATER TEMPS ARE HEATING ACCURATELY. (JPS) WARRANTY VERIFIED THIS TO BE CORRECT (SPD)

CORRECTION: WILL GO OVER ISSUE WITH CUSTOMER

W/O: 26801
Promised Date: 30 MAR 26



Customer #: 93045
SWIFT, AUBURNI



Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CS THE SLIDE REAR SLIDE IS LEAVING BLACK MARKS ON UNIT WHEN OPENING CLOSING

CAUSE: EXCESS PUTTY FROM SLIDE FASCIA HAS GOTTEN ON SLIDE SEAL AND IS TRACKING/SMEARING ACROSS EXT SLIDE WALL.

CORRECTION: NEED TO REMOVE THE EXCESSIVE PUTTY AND CLEAN AREA
LABOR .50

Labor

Job #	Description	Hours	Total
8	REMOVED PUTTY AND CLEANED	0.50	87.50

Subtotal for Job #8: 87.50

Parts Total: 47.26

Labour Total: 472.50

Sublet Total: 0.00

Extras Total: 26.42

WORK ORDER TOTAL: 546.18

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 13 Apr 2026

Customer Signature : _____

W/O: 26801
Promised Date: 30 MAR 26



Customer #: 93045
SWIFT, AUBURNI

