



Pre-Authorization

Pre-Authorization number

PREAUTH97101(PA03988489)

Reference no.26990

Status

Denied

Servicing Dealer 8140

Name Tri-AM RV Center of East TN

Address 1202 Idell Rd
Bulls Gap, TN 37711

VIN 4YDFAAU25TZ915030

Retail sold on

Root		Approved		Actual	Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	
3300706B	Chair - Freestanding Dinette - 0 Replace	0.5	0			1	Complaint: At the dinette table, one side has 2 chairs and a bench on the other side. The bench does not have a back that is attached, when you move the bench to eat, the back stays on the wall Cause: Bench has no back that stays on when customer moves it to eat. The table is too far away from the bench to not move it up to eat Correction: Need to replace the bench with the 2 chairs on the other side of the table KRV — Unit built in accordance with current manufacturing specifications.
Pre-Authorization number: PREAUTH97101			0				

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.