



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 2937 RIGHTMYER, RICKY



Estimate: 2937

Customer: 91315 - RIGHTMYER, RICKY
Address: 3426 SUNNYDALE RD
GREENEVILLE, TN
37743
Home Phone: 754-224-8444
Work Phone:
Author: CLP
Location: IH
Invoice #:

Stock #:
Stock Desc: 2019 C FOREST RIVER FORESTER
3041
Model: 3041
Serial #: 1FDXE4FS5KDC02890
Chassis #:
Mileage: 16286
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 21 NOV 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CUSTOMER STATES LEAK FROM CLAIM CAUSED WATER DAMAGE TO ELECTRONICS

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	14.88	14.88

Subtotal for Job #1: 14.88

Job #2 - External

REPLACE TOUCH PANEL

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE TOUCH PANEL AND PROGRAM	0.50	175.00	87.50

Other Services

Code	Description	Qty	Price	Total
NII	TOUCH PANEL	1	820.99	820.99

Subtotal for Job #2: 908.49

Job #3 - External

REPLACE LIGHT CONTROL ASSEMBLY

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE AND REWIRE LIGHT ASSEMBLY	1.20	175.00	210.00

Other Services

Code	Description	Qty	Price	Total
NII	LIGHT CONTROL ASSEMBLY	1	281.99	281.99

Subtotal for Job #3: 491.99

Parts Total: 0.00
Labour Total: 297.50
Sublet Total: 0.00
Extras Total: 1,117.86
Tax Total: 138.00
Estimate Total: 1,553.36

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer Signature : _____

Date: 25 Nov 2025

