



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 26752 CLARK, BRIAN



Estimate: 26752 (Appointment Date: 23 FEB 2026 - Time: 09:00am)

Customer: 74128 - CLARK, BRIAN
Address: 326 ROYAL ST
GREENEVILLE, TN
37745

Home Phone: 423-620-4071

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11125

Stock Desc: 2017 TT KEYSTONE COLEMAN
262BH

Model: 262BH

Serial #: 4YDT26224HH933550

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 11 JUN 25

Date In: 21 FEB 26

Promise Date: 01 MAR 26

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 11 JUN 25

Job #1 - External

SCRAPE AND SEAL

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Parts

Part #	Description	Qty	Price	Total
JR10061	VINYL INSERT 50' BLK	0	21.59	0.00
38-9018	LAP SEALANT WHITE	0	12.59	0.00

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

CUST WOULD LIKE TO SEE IF THERE IS ANY OPTIONS FOR A BIKE RACK

Subtotal for Job #3: 0.00

Job #4 - External

CUST WOULD LIKE TO KNOW THE COST ON COVERS FOR THE UNIT



Subtotal for Job #4: 0.00

Job #2 - External

CS THAT THEY WOULD LIKE TO GET THE FRONT SCREW COVER REPLACED

Subtotal for Job #2: 0.00

Job #5 - External

CS THAT THE COVER ON THE REAR MARKE LIGHT LENS HAS COME OFF REINSTALL

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Feb 2026

