



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 2974 MOODY, CONNIE



Estimate: 2974

Customer: 89252 - MOODY, CONNIE
 Address: 738 SPEEDWELL RD
 BULLSGAP, TN
 37711

Home Phone: 870-416-1791

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
 Stock Desc: 2017 A WINNEBAGO VISTA LX
 Model:
 Serial #: 1F65F5DY7H0A13344
 Chassis #:
 Mileage: 1212
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 01 APR 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #1 - External

REPLACE ROOF WITH TPO AFTER TREE DAMAGE

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACE ROOF	40	175.00	7,000.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	50.00	50.00
NII	TPO	1	783.99	783.99
NII	INSTALL KIT	1	405.99	405.99
NII	SEALANT	6	13.99	83.94
NII	BUTTYL	2	12.99	25.98

Subtotal for Job #1: 8,349.90

Job #2 - External

REMOVE AND REINSTALL AIR CONDITIONER

Other Services

Code	Description	Qty	Price	Total
NII	AC GASKET	1	60.99	60.99

Subtotal for Job #2: 60.99

Job #3 - External

REMOVE AND REINSTALL VENTS

Subtotal for Job #3: 0.00

Job #4 - External

REMOVE AND REINSTALL ANTENNA



Subtotal for Job #4: 0.00

Job #5 - External

REPLACE MAX AIR FANS

Other Services

Code	Description	Qty	Price	Total
NII	MAXXAIR	2	315.99	631.98

Subtotal for Job #5: 631.98

Job #6 - External

REMOVE AND REINSTALL AWNING RAIL

Subtotal for Job #6: 0.00

Job #7 - External

INSTALL NEW SIDE RAILS

Other Services

Code	Description	Qty	Price	Total
NII	GUTTER RAIL 16'	4	45.99	183.96

Subtotal for Job #7: 183.96

Job #8 - External

INSTALL FRONT CAP RAIL

Other Services

Code	Description	Qty	Price	Total
NII	FLAT MOLDING	1	29.99	29.99

Subtotal for Job #8: 29.99

Job #9 - External

INSTALL REAR CAP RAIL

Other Services

Code	Description	Qty	Price	Total
NII	CORNER MOLDING	1	0.00	0.00

Subtotal for Job #9: 0.00

Job #10 - External

CUT AND REMOVE FIBERGLASS

Labor

Code	Description	Hours	Rate	Total
Z990	CUT AND REMOVE FIBERGLASS	12	175.00	2,100.00

Subtotal for Job #10: 2,100.00

Job #11 - External

CUT AND REDECK ROOF

Labor

Code	Description	Hours	Rate	Total
Z990	REDECK ROOF	8	175.00	1,400.00

Other Services

Code	Description	Qty	Price	Total
NII	WOOD	6	45.99	275.94
NII	GLUE	8	7.99	63.92

Subtotal for Job #11: 1,739.86



Job #12 - External
 INSTALL RADIUS METAL

Labor				
Code	Description	Hours	Rate	Total
Z990	INSTALL METAL	3	175.00	525.00

Other Services				
Code	Description	Qty	Price	Total
NII	METAL	4	44.99	179.96

Subtotal for Job #12: 704.96

Job #13 - External
 REMOVE AND REINSTALL INTERIOR FASCIA, BULB SEAL, AND REPLACE SLIDE MOTOR

Labor				
Code	Description	Hours	Rate	Total
Z990	INSTALL MOTOR	2	175.00	350.00

Other Services				
Code	Description	Qty	Price	Total
NII	SLIDEMOTOR	1	941.99	941.99

Subtotal for Job #13: 1,291.99

Job #14 - External
 SUPPLEMENT FOR SHIPPING AND CRATING WILL BE SENT ONCE INVOICES ARE RECEIVED

Subtotal for Job #14: 0.00

Parts Total:	0.00
Labour Total:	11,375.00
Sublet Total:	0.00
Extras Total:	3,718.63
Tax Total:	1,471.62
Estimate Total:	16,565.25

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 01 Apr 2026

