



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25674 PETERSON,
ROBERT



Estimate: 25674 (Appointment Date: 26 JUN 2025 - Time: 09:00am)

Customer: 60472 - PETERSON, ROBERT

Address: 849 PATIENCE RD

BYBEE, TN

37713

Home Phone: 423-613-5758

Work Phone:

Author: CLP

Location: IH

Invoice #: 419059

Stock #:

Stock Desc: 2023 C COACHMAN FREELANDER

23FS

Model: 23FS

Serial #: 1FDXE4FN7RDD14711

Chassis #:

Mileage: 9773

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 26 JUN 25

Promise Date: 30 JUL 25

Promise Time: 09:00am

Schedule Date:

Completed: 26 JUN 25

Warr. Date:

Job #1 - External

COMPLAINT: CUS HAS NO 110 POWER IN UNIT CHECK AND ADVISE

CORRECTION: FOUND THAT THE UNIT HAS LIPO BATTERIES IN UNIT AND CONVERTER IS NOT COMPATIBALE WITH THIS SET UP

Labor

Code	Description	Hours	Rate	Total
Z990	DIAG	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
JR10071	VINYL INSERT 50' WHT	0	18.89	0.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: CHANGE OIL ON ENGINE

CORRECTION: CHANGED OIL

Labor

Code	Description	Hours	Rate	Total
Z990	OIL CHANGE	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
1372	OIL FILTER	0	15.29	0.00
5W30	OIL 5W30 QT	0	7.19	0.00

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CS THAT THEY HAVE AN ALARM THAT GOES OFF FOR THE JACKS BEING DOWN
CHECK AND ADVISE

CAUSE: FOUND TAHT THE CONTROL BOARD HAS FAILED NEEDS NEW PANEL

Labor

Code	Description	Hours	Rate	Total
Z990	DIAG	0	175.00	0.00



Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Jun 2025

