



# KEYSTONE

## Pre-Authorization

Pre-Authorization number: PREAUTH879 (PA03979619) Reference no. 79145 Status: Approved

Service Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd VIN 4YDTCGK21TV500085 Retail sold on 3/19/2026  
 Evansville, IN 47725

Root	Operation Description	Sublet	Sub Hours	Approved Hours	Actual hours	Qty	Base hours	Complaint/Cause/Correction
6201106B	Regulator - Replace	0	0.5	0.5		1	0.3	<p><b>Complaint:</b> REGULATOR IS NOT HOLDING PRESSURE</p> <p><b>Cause:</b> Regulator</p> <p><b>Correction:</b> During final pdi regulator bottomed out when adjusting for drop test. Removed regulator from main line. Removed regulator for unit. Removed arms from regulator. Placed arms on new regulator. Placed mounting bracket on new regulator. Attached new regulator to main line after putty thread tape on line and tightened down. Placed on unit and checked for leaks. None found.</p>

KRV-VCB

Pre-Authorization number: PREAUTH87921 0.5

For paper claims only use one pre-authorization number per warranty claim form.  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.  
 The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.