

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS Paid	
MYERS RV CENTER INC		CLAIM 2559988	
12024 CENTRAL AVE S.E.		CLAIM ORIGIN WEB	
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC3TG815373
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16BHX-452
JAMES GRIEGO		DEALER RO #	72578
1911 LOS LENTES RD NE		CLAIM START DATE	01/23/2026
Los Lunas, NM 87031		CLAIM END DATE	04/21/2026
USA			
Retail Date of Purchase	03/27/2026	WARRANTY EXPIRATION DATE	03/27/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:24:39 :: Right and left rear decals are bubbling. Found an adhesion failure. Replace rear black decals x2.			
	Model#	Dlr Sub Hrs	2.00	Sub Labor Amt \$380.00
	Serial#	Appr Hrs	2.00	Appr Labor Amt \$380.00
	Notes			
	NVCB,R&R large decals on both sides.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Part

Line# 1	Item # F100731344	Description GRAPHIC, DC 4 LH, AVENGER 2026, 171018	
	Model #	Serial #	Part tag
	Sub Qty 1.00	Sub Dlr Price \$11.20	Sub Freight \$16.28
	Appr Qty 1.00	Appr Dlr Price \$11.20	Appr Freight \$16.28
	Notes		
Line# 2	Item # F100731370	Description GRAPHIC, DC 4 RH, AVENGER 2026, 171019	
	Model #	Serial #	Part tag
	Sub Qty 1.00	Sub Dlr Price \$11.20	Sub Freight \$16.43
	Appr Qty 1.00	Appr Dlr Price \$11.20	Appr Freight \$16.43
	Notes		

Labor

Line# 2	Operation Code	Operational Description		
	20-46-01-00-000731	Window Latches - Exterior/Windows/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:25:49 :: Complaint: emergency exit window lever tab is broken Cause: Broken tab Correction: Replace lever			
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00	
	Notes			
	NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of			

repair code have been met.TD

Part Line#	Item #	Description
1	20X70718A	EXIT LATCH EXIT LATCH for VEPW, RED HANDLE SILVER ARM, 389567
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$33.53
	Appr Qty 1.00	Appr Dlr Price \$33.53
		Part tag
		Sub Freight \$16.64
		Appr Freight \$16.64
	Notes	

Submitted	Labor Amt	\$437.00	Approved	Labor Amt	\$418.00
	Parts & Freight	\$105.28		Parts & Freight	\$105.28
	Total	\$542.28		Total	\$523.28

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.