



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72979
Promised Date:
NE MAB 26

72979

WO #: 72979

Customer Name: 61263 - EBERTING,
WILLIAM DARRELL

Completed Date:
Invoice#:
Author: J.LINDAMAN
Stock Desc: 9535 2025 OPEN RANGE
20FBS
Serial#: 58TBM0BK5S75C3110
Chassis#: 58TBM0BK5S75C3110
Miles/Hrs:
Tag#:
Purchased Date: 28 FEB 26
Warranty Date: 05 MAR 26

Date In: 28 FEB 26
Time In:

Job #PDI2 - Internal

COMPLAINT: SFD NEW TT & INSTALL BATTERY - 1.5

CAUSE: Sfd travel trailer

CORRECTION: Complete
We owe added

Labor

Job #	Description	Total
PDI2	SFD TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
SRM-29	31 SERIES BATTERY	1.00	N/C	N/C
89-1303	BATTERY BOX - LARGE	1.00	N/C	N/C
92-8592	COUPLER SAFETY PIN 5/16"	1.00	N/C	N/C
18869	CARABINER, SNAP HOOK 3"	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI2: 0.00

Job #1 - External

COMPLAINT: Drivers side fender skirt has large crack
It is cut most of the skirt is on the slide room small piece on the unit itself over all approximately 66 inches

CORRECTION: REFERANCE WO#73003

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: Water does not work
Has 13.2 DCV to the pump will not turn on

CAUSE: Water pump would not operate

CORRECTION: During sfd found water pump would not turn on
Check power to the quick connectors had 13.2dcv

Customer #: 61263
EBERTING, WILLIAM
DARRELL

61263

72979

Customer #: 61263
EBERTING, WILLIAM
DARRELL

61263

Disconnected pump from the water lines and unscrewed it from the floor
Found the black wire was badly pinched up against the wall of the cabinet
Bench tested the pump and it began to run
Connected to the unit power and was operating
Reconnected water lines
Moved pump forward rescrewed it to the floor tested the water pump at all facets and toilet now pumping
water correctly
.50 REQUESTED

Labor		Total
Job #	Description	N/C
2	WATER SYSTEM	
Subtotal for Job #2:		0.00
Parts Total:		0.00
Labour Total:		0.00
Sublet Total:		0.00
Extras Total:		0.00
WORK ORDER TOTAL:		0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF
COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR
DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR
ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and
materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts
shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle
herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An
express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 05 Mar 2026