



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27115

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11304

Stock Desc: 2026 TT KZ-RV CONNECT 293RB

Model: 293RB

Serial #: 4EZTL3026T4021843

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 04 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: THE WALL BATTEN AT THE ENTRY OF UNIT IS NOT ATTACHED AND COMING OFF

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK IN PLACE

LABOR .20

Subtotal for Job #1: 0.00

Job #3 - Warranty

COMPLAINT: CABINET DOORS ON THE BOTTOM OF CABINET INSIDE ENTRY ARE NOT CLOSING AND HITTING EACH OTHER. CABINET DOOR MAGNETS ARE NOT EVEN AS WELL

CAUSE: NOTED ON DAF

CORRECTION: REALIGN CABINET DOORS TO CLOSE CORRECTLY AND RELOCATE THE CABINET DOOR MAGNETS TO BE MORE EVEN

LABOR .40

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CABINET DOORS IN THE KITCHEN AREA ARE NOT CLOSING

CAUSE: NOTED ON DAF

CORRECTION: READJUST CABINET DOOR HINGES TO ALLOW THE DOORS TO CORRECTLY CLOSE

LABOR .30

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CABINET STILE AT TV HAS BLACK MARKS

CAUSE: NOTED ON DAF

W/O: 27115



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #5: 0.00

W/O: 27115

Job #6 - Warranty

COMPLAINT: WARDWROOBE CLOSET DOORS HITTING AND NOT CLOSING ALL THE WAY

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGES ON CABINET DOORS TO SHUT CORRECTLY
LABOR .20

Subtotal for Job #6: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 04 May 2026

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

