

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2665646
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT3CS2B7TG128597
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 049 / 049B
 ITEM # CSFFAM37
 DEALER RO # 73099-1
 CLAIM START DATE 05/05/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-99-24-00-001015 Mini-Blind - Interior/Soft Goods/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:02:43 :: Complaint: Kitchen blinds are detached, valance needs to be taken down, blinds need to be reconnected and valance reinstalled Cause: Blinds fell during transport Correction: Remove the upper valance, attached the blinds to the blind hooks, rehung valance, checked operation

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$19.00

Notes
 Authed for a reasonable amount to reattach blinds

Labor

Line# 2 **Operation Code** **Operational Description**
 30-91-24-00-004733 Ottoman with Tabletop and Cushion - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:06:57 :: Complaint: Small scratch on wood table in living room Cause: Scratch on table from transport Correction: Used paint marker and filled in the discoloration, then got a rag and wiped off the excess color.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$57.00

Notes
 Authed

Labor

Line# 3 **Operation Code** **Operational Description**
 10-9-02-11-000204 Sensing Unit - Frame & Chassis/Levelers, Underbelly/Adjust/Electrical
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:10:06 :: Complaint: Left side leveling jack had an error code Cause: Jacks had an error code Correction: The unit was just on unlevel ground, was able to adjust up and down and it is working properly. Asking for time to test/setup.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs	0.25	Appr Labor Amt \$47.50

Notes
 Authed

Labor

Line# 4 **Operation Code** **Operational Description**
 30-101-01-00-001085 Sliding, Pocket Door Latch - Interior/Interior Doors/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-05 19:12:23 :: Complaint: Door securing latch pops

