

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2654468
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEXBXS030472
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	320 / 320
Labor rate:	\$195.00	ITEM #	FET320BHDS-320
OWNER INFORMATION		DEALER RO #	79649
		CLAIM START DATE	04/25/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-147-24-00-001769	TV Coax Cable - Appliances/Television/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-04-25 16:05:59 :: CAN NOT GET RECEPTION ON TV FROM ANTENNA. Tv antenna On inspection of the tv antenna i wasn't getting signal in. So i took the power booster out and checked the connections. And all were loose. So i checked continuity. In each cable that was good. So i tightened up all the connections and tv antenna works properly now			
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$136.50
Serial#	Appr Hrs	0.70	Appr Labor Amt	\$136.50
	Notes			
	R&RI TV power plate and test cables; R&RI splitter and test cables; tighten all connections			

Submitted	Labor Amt	\$136.50	Approved	Labor Amt	\$136.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$136.50		Total	\$136.50

DEALER
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

DATE

CUSTOMER
SIGNATURE

All repairs described have been inspected and are satisfactory.

DATE