



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$381.33

RO# : 40326 Tag# : TE760410

Check-in: Tue Mar 31, 2026 | 12:43 PM
Ready for Pickup: Fri May 8, 2026 | 12:07 PM
Promise Time: Sun Apr 5, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVR27 TE760410
1 Mi In
In Service Date:
01/01/2017
Sold Date: 04/30/2026
Stock #: KS26-34

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES THERES 3 JACK LIGHTS THAT DO NOT WORK	Warranty Pay	\$381.33
----	---------------	---	--------------	----------

Job added by KEVIN GOODIEL on Tue Mar 31, 2026 | 12:43 PM

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$38.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	1.05	1	1	\$165.00	\$38.00

1. Replaced the rear driver side light, then moved to the driver middle. One of the screws holding the light on the jack had a stripped head, so had to break the old light to removed the screw with pliers. Took pics of the screw head before removal. Replaced front driver side light as well. Inspected the remaining lights and found the passenger middle light now has several lights burned out. Took pic.

Parts

Parts Total Sale Amount \$140.37

Parts Total Cost Amount \$107.97

Name	Quantity	Unit Price	Sale Price	Cost Price
727085 - Jack - Electric - LED Light Card - w/Deutsch Connector - Technomelt Coating	3	\$46.79	\$140.37	\$107.97

Fees \$75.96

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$75.96	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$381.33

RO# : 40326 Tag# : TE760410

Check-in: Tue Mar 31, 2026 | 12:43 PM
Ready for Pickup: Fri May 8, 2026 | 12:07 PM
Promise Time: Sun Apr 5, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVR27 TE760410

Service Advisor
KEVIN GOODIEL
goodielk

Total Labor Sale
\$165.00

Total Labor Cost
\$38.00

Total Parts Sale
\$140.37

Total Parts Cost
\$107.97

	Category	Sale	Cost
	Labor	\$165.00	\$38.00
	Parts	\$140.37	\$107.97
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$75.96	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$381.33	\$145.97

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Mon Apr 6, 2026	8:25 AM	9:28 AM	1.05 hrs	W	lafavet	1 hrs

Tag: Regular Hour

Reason: -

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40326	LINK RV	\$381.33
57200	40326	LINK RV	-\$165.00
67200	40326	LINK RV	\$38.00
14400	lafavet	LINK RV	-\$38.00





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$381.33

RO# : 40326 Tag# : TE760410

Check-in: Tue Mar 31, 2026 | 12:43 PM
Ready for Pickup: Fri May 8, 2026 | 12:07 PM
Promise Time: Sun Apr 5, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ALPINE
4YDFAVR27 TE760410

Service Advisor
KEVIN GOODIEL
goodielk

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
54200	40326	LINK RV	-\$140.37
64000	40326	LINK RV	\$107.97
14000	40326	LINK RV	-\$107.97
76710	40326	LINK RV	-\$75.96

