



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73356
 Promised Date:
 14 MAY 26



WO #: 73356

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9650 2026 AVENGER
 17DBX
 Serial#: 5ZT2AVFC0TG815460
 Chassis#: 5ZT2AVFC0TG815460
 Miles/Hrs:
 Tag#:
 Purchased Date: 23 APR 26
 Warranty Date: 16 MAY 26

Date In: 14 MAY 26
 Time In:

Job #1 - Warranty

COMPLAINT: REFER LOOSE

CAUSE: Refrigerator came loose from rear mounting bracket

CORRECTION: Well detail was cleaning the unit. They opened the refrigerator door to clean the inside of the refrigerator. The refrigerator came loose from the mounting bracket. Examining the refrigerator and how the factory installed it there was a self tapping screw drilled through the bottom hinge on the left side of the refrigerator door to hold it in the hole. Remove the screw pull the refrigerator out examine the mounting bracket it was still screwed in secured to the floor however, putting the refrigerator back in to test the mounting bracket was found the refrigerator would go too far into the cabinet not allowing the door to be opened. Move the mounting bracket forward approximately 1 inch lid. The refrigerator back in so it would fully lock into the base mounting bracket on the rear. Now the refrigerator will not tip out or tip forward the original screw that was run through the hinge was put back into place. The refrigerator now will not come out of the cabinet or fall out or tip forward.

.70HRS

Labor

Job #	Description	Total
1	REFRIGERATOR DIAGNOSTIC TIME	N/C

Subtotal for Job #1: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 14 May 2026

Customer Signature : _____

Customer Work Order

W/O: 73356
Promised Date: 15 MAY 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

