



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73138
 Promised Date:
 18 APR 26



WO #: 73138 (Appointment Date: 02 APR 2026 - Time: 09:15am)
 Customer Name: 58933 - SPRINKLE JR, JAMES KENT
 Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9478 2025 BAY STAR 3225
 Serial#: 142117
 Chassis#: 1F66F5DN0R0A02245 Date In: 01 APR 26
 Miles/Hrs: 4681 Time In:
 Tag#: 7097
 Purchased Date: 18 FEB 25
 Warranty Date: 18 FEB 25

Job #1 - External

COMPLAINT: CUSTOMER STATES REAR AC HAS ERROR CODE E5

CAUSE: Fan attempts to run. Once compressor call out is made, E5 code is thrown. Inspected wiring.
 Possible compressor lock out

CORRECTION: Replace roof unit
 2.0

Labor

Job #	Description	Total
1	A/C DIAGNOSTIC TIME	185.25

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	17.71	17.71

Subtotal for Job #1: 202.96

Job #2 - External

COMPLAINT: CUSTOMER STATES GRAY TANK WILL NOT REGISTER PROPERLY

CAUSE: Attempted tank sensor recalibration. Unsuccessful. Bad sensor. Fluctuating between 85% and true reading of 15%

CORRECTION: Replace sensor 2.0

Labor

Job #	Description	Total
2	MONITOR PANEL DIAGNOSE	142.35

Parts

Part #	Description	Qty	Price	Total
13-0108	AQUA-MAX 32OZ LIQUID	1.00	12.95	12.95

Subtotal for Job #2: 155.30

Job #3 - External

COMPLAINT: CUSTOMER STATES PASSENGER REAR DOOR STRUT BROKEN

CAUSE: Ball mount damaged. Strut damaged. Compartment door damaged

Customer #: 58933
 SPRINKLE JR, JAMES
 KENT



CORRECTION: Order and replace both strut mounts and strut. Bend compartment door to allow for strut movement
1.0

Labor		
Job #	Description	Total
3	COMPARTMENT DOOR GAS STRUT R&R	9.75
Subtotal for Job #3:		9.75

Job #4 - External
COMPLAINT: CHANGE ENGINE OIL

CORRECTION: CHANGED ENGINE OIL

Labor		
Job #	Description	Total
4	MISC LABOUR CODE (WARRANTY)	0.00
Sublet		
Description	Total	
CHANGE ENGINE OIL	389.75	
Subtotal for Job #4:		389.75

Parts Total:	12.95
Labour Total:	337.35
Sublet Total:	389.75
Extras Total:	17.71
Tax Total:	57.78
WORK ORDER TOTAL:	815.54

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 05 May 2026

W/O: 73138
Promised Date: 10 APR 26



Customer #: 58933
SPRINKLE JR, JAMES
KENT

