

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
GREENEWAY INC
DBA GREENEWAY RV SALES & SERVICE
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS, WI 54494
USA

CLAIM STATUS Paid
CLAIM 2665178
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 4X4TFLL25MZ176287
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 010 / 010D
ITEM # FLT29RLBS
DEALER RO # 13425
CLAIM START DATE 05/05/2026
CLAIM END DATE 05/08/2026

Labor rate: \$140.00

OWNER INFORMATION

JON SHILLING
8855 W. Travis Ln
Franklin, WI 53132
USA

Retail Date of Purchase 09/17/2021

WARRANTY EXPIRATION DATE

09/17/2022

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	SB-670-05-00-004081	51-1377 - LIPPERT VENTURE ELECTRIC ACTUATORS - INSPECT - Technical Service Bulletin/Actuator/Inspect/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2026-05-05 14:50:23 :: Complaint: Recall needed 51-1377
Cause: Lowered underbelly, pics and measurements taken starting with the rear slides and front slide last.
Correction: Recall inspection.

Model#	Dlr Sub Hrs	1.30	Sub Labor Amt	\$182.00
Serial#	Appr Hrs	1.30	Appr Labor Amt	\$182.00

Notes

Hello, this doesn't appear to need the replacement actuator. The part number on the motor is not the one the recall is for and neither serial number matches the affected ones.
Yes, this is for inspection only. This recall comes up on this VIN number.
Authorized for the inspection of two actuators, neither fell under recall. Underbelly was removed which is the increased time of 1hr on top of flat rate. Thank you!

Submitted	Labor Amt	\$182.00
	Parts & Freight	\$0.00
	Total	\$182.00

Approved	Labor Amt	\$182.00
	Parts & Freight	\$0.00
	Total	\$182.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.