




12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73204  
 Promised Date:  
 15 APR 26



WO #: 73204  
 Customer Name: 59670 - LOPEZ,  
 PATRICK JOSEPH

Completed Date: 13 MAY 26  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9328 2024 TRACER  
 200BHSLE  
 Serial#: 5ZT2TRJB7RB524623  
 Chassis#: 5ZT2TRJB7RB524623  
 Miles/Hrs:  
 Tag#: STORAGE 10  
 Purchased Date: 10 APR 25  
 Warranty Date: 10 APR 25

Date In: 15 APR 26  
 Time In:

**Job #0 - Warranty**  
 CLAIM: 2644922

**Subtotal for Job #0: 0.00**

**Job #1 - Warranty**  
 COMPLAINT: CUSTOMER STATES DINETTE WINDOW WILL NOT OPEN

CAUSE: Warped window track

CORRECTION: The window track was warped due to the sun I cleaned the old track and at that time I noticed that warping-the screen was removed and I was able to slide out the old track. The frame was clean from the debris the new track was fitted and screwed in. The track was placed back into the frame. The screen was placed back into the frame of the window. The window slides from end to end without any obstruction.

Photos attached

**Labor**

| Job # | Description       | Total |
|-------|-------------------|-------|
| 1     | WINDOW GASKET R&R | 76.00 |

**Parts**


| Part #     | Description   | Qty  | Price | Total |
|------------|---|------|-------|-------|
| F100411825 | WINDOW TRACK, SLIDER TRACK<br>PRE-PUNCHED (349189-RV28274-03) | 6.00 | 0.87  | 5.22  |

**Other Services**

| Code | Description                    | Qty  | Price | Total |
|------|--------------------------------|------|-------|-------|
| FRT  | SHIPPING & HANDLING<br>CHARGES | 1.00 | 56.43 | 56.43 |

**Subtotal for Job #1: 137.65**

Customer #: 59670  
 LOPEZ, PATRICK JOSEPH



Parts Total: 5.22  
Labour Total: 76.00  
Sublet Total: 0.00  
Extras Total: 56.43  
**WORK ORDER TOTAL: 137.65**

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 13 May 2026

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 73204  
Promised Date: 15 APR 26



Customer #: 59670  
LOPEZ, PATRICK JOSEPH

