



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73163  
 Promised Date:  
 11 APR 26



WO #: 73163  
 Customer Name: 61429 - MARQUEZ,  
 ANGEL SERGIO

Completed Date: 15 APR 26  
 Invoice#:  
 Author: J.LINDAMAN  
 Stock Desc: 9581 2026 AVENGER 27REI  
 Serial#: 5ZT2AVSB2TB941118  
 Chassis#: 5ZT2AVSB2TB941118  
 Miles/Hrs:  
 Tag#:  
 Purchased Date: 11 APR 26  
 Warranty Date: 11 APR 26

Date In: 07 APR 26  
 Time In:

**Job #0 - Warranty**

CLAIM: 2642197

**Subtotal for Job #0: 0.00**

**Job #1 - Internal**

COMPLAINT: DEWINTERIZE

CAUSE: Dewinterize

CORRECTION: Completed

**Labor**

| Job # | Description | Total |
|-------|-------------|-------|
| 1     | DEWINTERIZE | N/C   |

**Subtotal for Job #1: 0.00**

**Job #2 - Internal**

COMPLAINT: 8K EQ EASLIFT ELITE S

CAUSE: New install

CORRECTION: Complete  
 Estimated Amount: 553.00

**Labor**

| Job # | Description           | Total |
|-------|-----------------------|-------|
| 2     | INSTALL EQUALIZER KIT | N/C   |

**Parts**

| Part # | Description                    | Qty  | Price | Total |
|--------|--------------------------------|------|-------|-------|
| 48192  | EQ HITCH - EAZ-LIFT ELITE-S 8K | 1.00 | N/C   | N/C   |

**Subtotal for Job #2: 0.00**

**Job #3 - Internal**

COMPLAINT: Rear power stabilizer jacks bent.

CAUSE: Replace

CORRECTION: Completed

Customer #: 61429  
 MARQUEZ, ANGEL SERGIO





| <b>Labor</b> |               |  |  |       |
|--------------|---------------|--|--|-------|
| Job #        | Description   |  |  | Total |
| 3            | REPLACE JACKS |  |  | N/C   |

  

| <b>Parts</b> |  |      |       |       |
|--------------|--|------|-------|-------|
| Part #       | Description                                | Qty  | Price | Total |
| 09-1383      | ELECTRIC STABILIZER JACK PSX1 W/<br>SWITCH | 1.00 | N/C   | N/C   |

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: Front cap trim loose on passenger side

CAUSE: Resecured

CORRECTION: Completed  
.25HRS

| <b>Labor</b> |               |  |  |       |
|--------------|---------------|--|--|-------|
| Job #        | Description   |  |  | Total |
| 4            | RESECURE TRIM |  |  | 38.00 |

**Subtotal for Job #4: 38.00**

**Job #5 - Internal**

COMPLAINT: Summit tv remote missing

CORRECTION: STEAL FROM ANOTHER AVENGER.

| <b>Labor</b> |                |  |  |       |
|--------------|----------------|--|--|-------|
| Job #        | Description    |  |  | Total |
| 5            | REPLACE REMOTE |  |  | N/C   |

**Subtotal for Job #5: 0.00**

**Job #6 - Internal**

COMPLAINT: Bathroom sink - water lines switched  
hot was cold & cold was hot

CAUSE: Cold and hot lines switched in bathroom

CORRECTION: During orientation it was found the bathroom sink hot and cold lines were switched giving the appearance the water heater was not working  
Tested the water on the cold side water heater works correctly  
Switched the water lines now correct  
.10HRS

| <b>Labor</b> |             |  |  |       |
|--------------|-------------|--|--|-------|
| Job #        | Description |  |  | Total |
| 6            | WATER LINES |  |  | N/C   |

**Subtotal for Job #6: 0.00**

**Job #7 - Internal**

COMPLAINT: Front cap lights loose

CAUSE: Front cap lights hanging down out of the rail

CORRECTION: Found the cap lights in the insert corner molding were hanging down out of the rail about 2 inches  
Pushed he lights back in place and crimped the ends so they will stay in place  
Work completed  
.10HRS



| Labor                       |             |             |
|-----------------------------|-------------|-------------|
| Job #                       | Description | Total       |
| 7                           | CAP LIGHTS  | N/C         |
| <b>Subtotal for Job #7:</b> |             | <b>0.00</b> |

**Job #PDI2 - Internal**

COMPLAINT: SFD NEW TT & INSTALL BATTERY - 1.5

CAUSE: Sfd

CORRECTION: Completed

See added jobs

| Labor |                    |       |
|-------|--------------------|-------|
| Job # | Description        | Total |
| PDI2  | SFD TRAVEL TRAILER | N/C   |

| Parts   |                          |      |       |       |
|---------|--------------------------|------|-------|-------|
| Part #  | Description              | Qty  | Price | Total |
| 92-8592 | COUPLER SAFETY PIN 5/16" | 1.00 | N/C   | N/C   |
| 1000    | L.P. GAS                 | 5.00 | N/C   | N/C   |
| 18869   | CARABINER, SNAP HOOK 3"  | 1.00 | N/C   | N/C   |
| SRM-29  | 31 SERIES BATTERY        | 1.00 | N/C   | N/C   |

| Other Services                 |               |      |       |             |
|--------------------------------|---------------|------|-------|-------------|
| Code                           | Description   | Qty  | Price | Total       |
| SS                             | SHOP SUPPLIES | 1.00 | N/C   | N/C         |
| <b>Subtotal for Job #PDI2:</b> |               |      |       | <b>0.00</b> |

|                          |              |
|--------------------------|--------------|
| Parts Total:             | 0.00         |
| Labour Total:            | 38.00        |
| Sublet Total:            | 0.00         |
| Extras Total:            | 0.00         |
| <b>WORK ORDER TOTAL:</b> | <b>38.00</b> |

NOTICE:  
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : \_\_\_\_\_

Date: 14 May 2026