



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 27153 PRUITT, RHEALYNN



Estimate: 27153 (Appointment Date: 20 MAY 2026 - Time: 09:00am)

Customer: 91159 - PRUITT, RHEALYNN
 Address: 1709 BUTTERFLY CT
 WHITESBURG, TN
 37891

Home Phone: (865) 548-1983

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
 Stock Desc: 2023 MPG UL CRUISER
 Model:
 Serial #: 5RXHB2626P1518116
 Chassis #:
 Mileage:
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 13 MAY 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #1 - External

CUSTOMER STATES WATER IS COMING FROM THE UNDERBELLY OF UNIT. WHEN THEY HOOK WATER UP, IT DOES NOT COME THRU ANY FAUCETS IN THE CAMPER, IT ALL GOES UNDERNEATH. STATES EXTENDED WARR, AND WILL BEING INFO

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
Subtotal for Job #1:				0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION
 CHECK CAULKING _____
 CHECK SKYLIGHTS _____
 CHECK ROOF VENTS _____
 CHECK LUBE & ANTENNA _____
 CHECK SATELLITE _____
 CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

CUSTOMER REQUESTING TO HAVE TIRE PRESSURE CHECKED, AND SEE IF WORN AND NEED REPLACED

Subtotal for Job #3: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
 Tax Total: 0.00
 Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 22 May 2026

