

ATTN:

DATE:

Coleman-Mach®

An AIRXCEL Brand

RVP TECH: ONLINE

TRACKING #: BLANKET

COOLING PERFORMANCE WORKSHEET

❖THIS IS NOT A CLAIM FORM❖

THIS FORM WILL NEED TO BE COMPLETED ENTIRELY, OR THE REQUEST WILL BE DENIED*This form cannot be submitted until all **required** sections have been completed and signed. Once you complete the signature field this form will automatically save a copy to your computer, then please click the SUBMIT button.*

COOLING PERFORMANCE CHECKOUT PROCEDURES:

SECTION 1: (Required)

FACILITY NAME: BASDEN AMERICAN RV CENTER		
ADDRESS: 600 E BASELINE		
CITY: EVANSVILLE	ST: IN	ZIP: 47725
PHONE: 8128675200		
EMAIL: BHOFFMAN@AMERICANRVCENTER.COM		

SECTION 3:

Does the compressor attempt to start?	☒ YES	☐ NO
Voltage to Unit?	118	VOLTS AC
Is the compressor tripping?	☐ OVERLOAD	☒ BREAKER
Amp Draw (black wire at compressor)?	46.3	AMPS
PTCR/Start Kit Good?	☐ YES	☐ NO
Ceiling Assembly Type:	☒ DUCTED ☐ NON-DUCTED ☐ NONE	

SECTION 5: (OEM INFO)

VIN: 4YDF31623M2508552
PRE-AUTHORIZATION #: PA02998645

IF THE AIR CONDITIONER IS RETURNED TO US, AND OUR DIAGNOSTIC CHECKOUT PROVES THE AIR CONDITIONER IS OPERATING PROPERLY, YOUR FIRM WILL BE CHARGED FOR THE AIR CONDITIONER AND ASSOCIATED FREIGHT COSTS.

❖If you don't receive a response within 24 hours, please contact us!❖

SUBMIT

SECTION 2: (Required)

AC/HP MODEL:	48254-6660
AC/HP SERIAL #:	210048769
DATE OF PURCHASE:	03-27-21
WHAT TYPE OF APPLICATION IS THIS UNIT INSTALLED ON?	2021 KEYSTONE COUGAR 316RLS
PO NUMBER:	N/A

SECTION 4:

To complete the following, you **MUST START and RUN** the unit in the **HIGH COOL** position for 15-20 minutes prior to taking **ANY** measurements.

DO NOT USE A LASER THERMOMETER

Outdoor Temperature:	°F
Temp at Return Air Grill:	°F
Temp at Supply Register:	°F

SECTION 6: (DEALER INFO)

DEALER NUMBER: 1194
ADVISOR NAME: BEN HOFFMAN

SECTION 7:

12/07/2021

NOTE: By signing and dating this form, you verify and guarantee the information as recorded above is truthful and accurate.

DATE



AUTHORIZED SIGNATURE OF RESPONSIBLE PARTY

If this form cannot be completed using Adobe Acrobat Reader, please download a copy, complete and email to RVPCPW@airxcel.com