

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Authorized CLAIM 2686834 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 4X4TRPU10TB036854 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 080 / 080 ITEM # RPT190-80 DEALER RO # 73380 CLAIM START DATE 05/26/2026 CLAIM END DATE 01/01/1900
--	---

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-147-01-11-003957	Connexx TV - Appliances/Television/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-26 09:08:18 :: Complaint: TV is damaged upon unit arrival Cause: Damaged during transport Correction: Remove and replace TV			
Model#	HV320WHB-F56	Dlr Sub Hrs	0.40	Sub Labor Amt \$76.00
Serial#	CX32A24DCS-1025-226-0512	Appr Hrs	0.30	Appr Labor Amt \$57.00

Notes

did the transport company note this, on there papaer work. ? the tv being damaged.
 It was noted at the time of delivery, but it got noted on the DAF for a different unit. The paperwork got switched up in error.
 i would need the paper work from the transport company where they notate there findings, to see if they notated this before leaving the factory lot.
 We don't have anything from the transport company, but I did upload the DAFs. So, the DAF for unit RPB036853 is ACTUALLY for RPB036854. As previously mentioned, the DAFs got flipped flopped in error, but the TB being scratched is noted.
 flat rate authorized to replace tv, thank you for providing and clarifing both daf.

Submitted	Labor Amt	\$76.00	Approved	Labor Amt	\$57.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$76.00		Total	\$57.00

DEALER **DATE**
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE
 All repairs described have been inspected and are satisfactory.