



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79755



CUSTOMER WORK ORDER

WO #: 79755

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0504 CHECK PREAUTH

Stock #: 11756
Stock Desc: 2026 5W KEYSTONE
COUGAR 30REP
Chassis #: 4YDFCGP25T2506575
Serial #: 4YDFCGP25T2506575
Mileage: 0
Licence:

Invoice #:
Date In: 29 APR 26
Promised:
Date Sched:
Completed: 30 APR 26
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: New PDI

CORRECTION: Torqued lugs to spec. Adjusted tire pressures to spec. Checked braking and emergency breakaway systems. Installed company decals. Filled and installed LP tanks. Tested running lights. Inspected exterior doors for fit and finish. Checked screen door. Checked slide function. Checked auto level system. Checked awning and awning light function. Inspected all exterior seals. Performed roof inspection. Inspected all cabinets, closets, and drawers. Tested all interior lights. Checked all windows and blinds. Tested LP system. Tested all appliances. Checked water system on pump and city connection. Performed LP drop test. Inspected all furniture. Inspected walls, ceiling, and floor.

Issues; bedroom cabinet doors are contacting each other. Shower head leaking. Patio door hard to close. AC remote not working.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	PCG	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Internal

COMPLAINT: SLIDING DOOR UNDR MICROWAVE WONT MOVE

CAUSE: Bad oem design. Wood track hard to open by design

CORRECTION: No correction needed

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	N/C

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: FRIDGE DOOR IS HARD TO LATCH SHUT

CAUSE: N/A

CORRECTION: No issues found

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SWITCH FOR PORCH IS PUSHING OUT

CAUSE: Wiring behind switch pushing it out

CORRECTION: Rearranged wiring and reinstalled switch

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	38.00

Subtotal for Job #3: 38.00

Job #4 - Warranty

COMPLAINT: BED ROOM CABINET DOORS ARE RUBBING

CAUSE: Hinges out of adjustment

CORRECTION: Adjusted hinges. Doors no longer contact

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	19.00

Subtotal for Job #4: 19.00

Job #5 - Warranty

COMPLAINT: SHOWER HEAD LEAKING

CAUSE: Seal needed to be reseated

CORRECTION: Reseated seal and pressure tested. No leaks

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	38.00

Subtotal for Job #5: 38.00

Job #6 - Warranty

COMPLAINT: PATIO DOOR IS HARD TO CLOSE

CAUSE: Door is unadjustable. Door plate is too thick

CORRECTION: Fabricated new plate out of sheet metal

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	PCG	0.00
Z990	MISCELLANEOUS REPAIR	PCG	95.00



Subtotal for Job #6: 95.00

Job #7 - Internal

COMPLAINT: A/C REMOTE IS NOT TALKING TO THE A/C

CAUSE: Remote was not calibrated

CORRECTION: Reset remote. Works properly

Labor Code	Description	Mechanic PCG	Total
Z990	MISCELLANEOUS REPAIR		N/C

Subtotal for Job #7: 0.00

Parts Total: 0.00
Labour Total: 190.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 190.00

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 May 2026

W/O: 79755



Customer #: 1000
BASDENS AMERICAN RV,

