



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM
Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARL28TE550253
1 Mi In / 1 Mi Out
In Service Date:
01/01/2017
Stock #: KS26-22

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES NO POWER CORD. TOOK PICTURES UNDER BED, OF BOTH CARGO BAYS, UNDER DINNETE BENCHES	Warranty Pay	\$391.11
----	---------------	---	--------------	----------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:31 PM

1. No power cord in the camper needs to order new 50 amp cord. Request 0.20hour

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$3.10

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
921	-	0.18	0	0	\$0.00	\$0.00
boiem	-	0	0	0	\$0.00	\$0.00
lafavet	-	0	0.1	0.1	\$16.50	\$3.10

1. No power cord in the camper needs to order new 50 amp cord

2. Put new cord in storage compartment on passenger side.

Parts

Parts Total Sale Amount \$323.27

Parts Total Cost Amount \$248.67

Name	Quantity	Unit Price	Sale Price	Cost Price
770591 - Cord - Shore/Power - 50A	1	\$323.27	\$323.27	\$248.67





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM
Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARL28TE550253	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

Fees \$51.34

Code	Description	Sale Amount	Cost Amount
FF	-	\$51.34	\$0.00

Total Labor Sale \$16.50	Total Labor Cost \$3.10	Total Parts Sale \$323.27	Total Parts Cost \$248.67
------------------------------------	-----------------------------------	-------------------------------------	-------------------------------------

B. MISCELLANEOUS	DEALER STATES FURNACE DOES NOT IGNITE	Warranty Pay	\$410.40
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:31 PM

1. Wire going to the thermal cut off was melted to the furnace, need to pull furnace and replace wire. Requesting 3 hours

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$247.50

Labor Cost: \$93.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
921	-	0	0	0	\$0.00	\$0.00
boiem	-	2.73	0	0	\$0.00	\$0.00
lafavet	-	0	3	3	\$247.50	\$93.00

1. Pulled furnace out to find the wire going from the board to the thermal cut off (TCO) was rubbing on the furnace and shorted the board out, took pictures. replaced the wire and board and the furnace started working like it should

Parts

Parts Total Sale Amount	\$162.90
Parts Total Cost Amount	\$125.31





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM
Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARL28TE550253	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$247.50
Labor Cost: \$93.00

Name	Quantity	Unit Price	Sale Price	Cost Price
03101474 - FAN CONTROL FOR FURNACE	1	\$162.90	\$162.90	\$125.31

Total Labor Sale \$247.50	Total Labor Cost \$93.00	Total Parts Sale \$162.90	Total Parts Cost \$125.31
-------------------------------------	------------------------------------	-------------------------------------	-------------------------------------

C. MISCELLANEOUS	DEALER STATES WOOD COVERS OVER THE DINETTE BENCHES DO NOT FIT AS THEY SHOULD. TRIM and/or wood cover needs trimming	Warranty Pay	\$82.50
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:31 PM

1. The dinette benches were not made perfectly square, Cut 1/8inch off the boards so they fit better and so they won't break when someone sits on them. Requesting .50

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$15.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
921	-	0	0	0	\$0.00	\$0.00
boiem	-	0.39	0	0	\$0.00	\$0.00
lafavet	-	0	0.5	0.5	\$82.50	\$15.50

1. The dinette benches were not made perfectly square, Cut 1/8inch off the boards so they fit better and so they won't break when someone sits on them

Total Labor Sale \$82.50	Total Labor Cost \$15.50	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM
Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARL28TE550253	Service Advisor KEVIN GOODIEL goodielk
---	---	--	---

D. MISCELLANEOUS	DEALER STATES THE STEPS HAVE A BROKEN ADJUSTMENT PIN	Warranty Pay	\$0.00
------------------	--	--------------	--------

Tags: Add-on

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:31 PM

1. locking pin on right leg is bent and will not pop out of hole. Request .50hour

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$6.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
921	-	0.02	0	0	\$0.00	\$0.00
boiem	-	0	0	0	\$0.00	\$0.00
lafavet	-	0.15	0.2	0.2	\$0.00	\$6.20

- Needs new leg on steps took pictures and got with parts to order
- Removed leg from steps. The push button on leg was bent into the leg interior, so it wasn't locking into the hole in steps like it should. Drilled the rivet that holds it out, then pulled the tab piece out and bent back into position, test fitting a couple times. Once set where it should be, installed new rivet, then put in step assembly.

Total Labor Sale \$0.00	Total Labor Cost \$6.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM

Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM

Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARL28TE550253

Service Advisor
KEVIN GOODIEL
goodielk

Category	Sale	Cost
Labor	\$346.50	\$117.80
Parts	\$486.17	\$373.98
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$51.34	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$884.01	\$491.78

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Dec 10, 2025	10:24 AM	10:34 AM	0.18 hrs	W	921	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Wed Dec 10, 2025	10:36 AM	10:37 AM	0.02 hrs	W	921	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Dec 10, 2025	11:22 AM	12:11 PM	0.81 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: Employee clocked out of the job for lunch break					
B	MISC	Wed Dec 10, 2025	12:52 PM	2:47 PM	1.92 hrs	W	boiem	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$884.01

RO# : 39862 Tag# : TE550253

Check-in: Mon Oct 27, 2025 | 3:31 PM
Ready for Pickup: Tue Apr 14, 2026 | 12:39 PM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARL28TE550253

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	Wed Dec 10, 2025	2:57 PM	3:20 PM	0.39 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Fri Apr 10, 2026	9:24 AM	9:24 AM	0 hrs	W	lafavet	3 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Mon Apr 13, 2026	2:39 PM	2:48 PM	0.15 hrs	W	lafavet	0.2 hrs
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	W	lafavet	0.1 hrs
C	MISC	-	-	-	0 hrs	W	lafavet	0.5 hrs
A	MISC	-	-	-	0 hrs	W	boiem	0 hrs
D	MISC	-	-	-	0 hrs	W	boiem	0 hrs
B	MISC	-	-	-	0 hrs	W	921	0 hrs
C	MISC	-	-	-	0 hrs	W	921	0 hrs

