



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27204



WO #: 27204

Customer: 93904 - DAMRON, WILLIAM  
Address: 112 COOK RD  
MOORESBURG, TN  
37811

Home Phone:  
Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11272  
Stock Desc: 2026 THTT FOREST RIVER ROGUE  
32L132  
Model: 32L132  
Serial #: 4X4TVGH22T5404111  
Chassis #:  
Mileage:  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date: 27 MAY 26  
Date In: 22 MAY 26  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date: 27 MAY 26

### Job #1 - Warranty

COMPLAINT: DURING PREP OF UNIT TECH FOUND WATER HEATER THROWING EC AND NOT WORKING

CAUSE: TECH DIAGNOSED THE BOARD HAD POWER COMING IN AND NONE GOING OUT DURING OPERATION AND A STRONG ELECTRICAL SMELL FROM MAIN BOARD

CORRECTION: DIAGNOSE AND REPLACE WATER HEATER CONTROL BOARD  
L 1.0

Subtotal for Job #1: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93904  
DAMRON, WILLIAM



Customer Signature : \_\_\_\_\_

Date: 22 May 2026

