

Warranty Authorization

Service Event 10375455

Date Created 5/14/2026



Page 1 / 1

Service Provider:

AMERICAN RV CENTER (SHIP TO)
600 E. BASELINE ROAD
Evansville, IN 47725
USA

Retail Customer

DEBRA LINDSEY

Customer number 10118021

Work order reference LINDSEY,D

Sales order 101573909

Return order

Serial number	Model on label	Sold as	Search name
54099583	0	R3310524FJ.521L	R/F POWER LED BLACK

Description : Scrap in Field

Note: Scrape data tag(s) off unit - apply to a blank piece of paper and email along with your repair order to claimpayments@dometic.com. Photos are accepted. The photos must show the tag(s) removed from the unit. Keep a copy of the data tag(s) for your records.

Description : 90 Day Return Policy

Note: ALL RETURNS AND WARRANTY CLAIMS MUST BE RECEIVED WITHIN 90 DAYS OF WARRANTY AUTHORIZATION DATE TO BE ELIGIBLE FOR REIMBURSEMENT. CLAIMS RECEIVED AFTER 90 DAYS WILL BE DENIED.

Customer complaint	TOO LONG
Component/part	R3310524FJ.521L
Component group	FABRIC
Service provider failure description	CUT INCORRECTLY
Resolution	PART REPLACED

Created

Labor	1.50
Parts	1.00

Dometic Corp. USA
8755 West Higgins Road, Suite 620
Chicago, IL 60631
USA

WEBSITE: www.dometic.com
PHONE: +1 502-873-3514

BANK: USLockbox
ACCOUNT: 8883133002
SWIFT 026010786

Return Order



Return Reason Code Customer reference Customer account

Returned by Returned to Delivery terms Page 1 / 1

Delivery mode

Carrier information

Item number	Description	Quantity	Unit price	Net amount
-------------	-------------	----------	------------	------------

Dometic Corp. USA
8755 West Higgins Road, Suite 620
Chicago, IL 60631
USA

WEBSITE: www.dometic.com
PHONE: +1 502-873-3514

BANK: USLockbox
ACCOUNT: 8883133002
SWIFT 026010786