

Pre-Authorization

Pre-Authorization number PA03015770 Reference no: 66147 Status: Approved Approved by gurlj Approved date 1/6/2022
Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGR21N3102253
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2101815B	Roof - Rubber Me	0.00	40.00	35.00		1	1.00	Complaint:THE INTERIOR CEILING LIGHT IN THE HALL NEAR THE BEDROOM AND BATHROOM ENTRANCE HAD WATER LEAKING THROUGH IT THE MORNING OF 12/18 WHICH WAS AFTER 2 DAYS OF RAIN Cause:I FOUND THAT OVER THE LIGHT, THE ROOFING WAS CUT TO FAR AT THE SEWER VENT. THE CUT IN THE ROOFING HAS LET RAIN WATER UNDER THE ROOFING AND IT WAS LEAKING INTO THE HALL LIGHT. I SEALED OVER THE CUT IN THE ROOFING. IT LOOKS LIKE 2 PEACES OF PLYWOOD WILL NEED TO BE REPLACED AND A NEW ROOF AFTER. Correction:INSTALL NEW DECKING AND INSTALL A NEW ROOF KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual to RR roof membrane and overlay decking.

Pre-Authorization number PA03015770

35.00For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company