

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville IN  
US  
47725  
812-867-5200

WORK ORDER # 66187

Completed : 17 JAN 22  
Licence # :  
Stock No : 10982  
Tag :  
Author : BH  
Location : 0115CHECKPREAUTH  
Serial# : 4YDFM0S20N4701454  
Warr. Date :  
Print Date : 17 JAN 22

Customer : 1013 - KEYSTONE RV CO -  
Invoice # :  
Description : 2022 5W KEYSTONE MONTANA 3231CK  
Date In : 27 DEC 21 Mileage : 0  
Promised :  
Date Sched :  
Chassis# : 4YDFM0S20N4701454  
Cust PO# :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*

PDIN COMPLAINT: PDI - NEW FIFTH WHEEL I PDI PRE-D  
CAUSE: PDINFW - PDI NEW FIFTH WHEEL.  
CORRECTION: Moved unit into shop from sales lot.  
Purged and filled (2) 30# LP tanks.  
Checked all exterior lights and brakes.  
Checked lug nuts and set tire pressure  
at 110 lbs. Operated auto jacks. Reset  
jacks to level unit. Checked entrance  
door and all compartment doors. Checked  
power cord. Checked all interior  
lights. Checked converter output.  
Checked both awnings. Checked roof.  
Checked all electrical outlets and GFCI  
outlets. Checked all USB outlets.  
Checked all windows and blinds. Checked  
all cabinets and drawers. Removed all  
packaging from Refrigerator. Microwave,  
Range and both TVs. Checked both TVs,  
TV Antenna, Radio. Fireplace and Vacuum.  
Recorded all serial numbers and took  
pictures. Performed LP drop test and  
set LP pressure at 11 in.wc. Operated  
all appliances. Applied all company  
decals. Filled all holding tanks and  
checked monitor panel. By-passed water  
heater and blew out all water lines and  
faucets, including outside shower.  
Added antifreeze to all water lines and  
faucets, including outside shower and  
washer faucets. Poured antifreeze in  
all drain traps. Drained all holding  
tanks, including water heater. Moved  
unit back to sales lot.

1 COMPLAINT: CEILING TRIM HANGING DOWN ON DINETTE W 1013 KEYST

Work Order : 66187

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To \*\*\*\*\*  
\*\*\*\*\*  
SLIDEOUT  
CAUSE: CEILING TRIM HANGING DOWN ON DINETTE  
SLIDEOUT.  
CORRECTION: Flat Ceiling trim too long and bowed.  
Trimmed end of flat trim and reattached  
to ceiling with brad nails.  
2 COMPLAINT: TRAILER DOES NOT HAVE A OUTSIDE LP QUICK I PDI PRE-D  
CONNECT  
CAUSE: tRAILER DOES NOT HAVE A OUTSIDE LP QUICK  
CONNECT.  
CORRECTION: Unit does not have quick connect for  
outside grille. Lp line is there but  
has plug in end of line. Can not do a  
LP drop test. Made up fittings and  
quick connect and installed on end of LP  
line. Checked all fitting s for leaks.  
All OK.

\*\*\*\*\*  
Job # Part No Description PARTS Bill to Qty Price Total \*\*\*\*\*  
\*\*\*\*\*  
PDINF 24181 -50 RV ANTI-FREEZE I-PDI 2 4.99 9.98  
2 06-0954 ME-GMCL-4P QUICK C I-PDI 1 44.99 44.99  
\*\*\*\*\*

\*\*\*\*\*  
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total \*\*\*\*\*  
\*\*\*\*\*  
DINFW Z991 PDI NEW FIFTH WHEEL (I DKM I-PDI 0.00 130.00 0.00  
DINFW Z991 PDI NEW FIFTH WHEEL (I DKM I-PDI 1.90 130.00 247.00  
DINFW Z991 PDI NEW FIFTH WHEEL (I DKM I-PDI 4.08 130.00 530.40  
DINFW Z991 PDI NEW FIFTH WHEEL (I DKM I-PDI 0.02 130.00 2.60  
1 Z990 MISCELLANEOUS REPAIR DKM W-1013 0.00 130.00 0.00  
1 Z990 MISCELLANEOUS REPAIR DKM W-1013 0.30 150.00 45.00  
2 Z990 MISCELLANEOUS REPAIR DKM I-PDI 0.32 120.00 38.40  
2 Z990 MISCELLANEOUS REPAIR DKM I-PDI 0.18 120.00 21.60  
\*\*\*\*\*

\*\*\*\*\*  
Job # Excode Description EXTRAS bill to Qty Price Total \*\*\*\*\*  
\*\*\*\*\*  
DINFW SS SHOP SUPPLIES I-PDI 1.00 35.00 35.00  
DINFW LP30 30LB. LP CYLINDER FILL I-PDI 2.00 20.00 40.00  
2 PARTS LP FITTINGS I-PDI 1.00 4.82 4.82  
\*\*\*\*\*

CUSTOMER COMMENTS

\*\*\*\*\*  
BH GOT APPROVEL  
BH SENT IN PREAUTH 1-8  
\*\*\*\*\*

Continued on page 3

Work Order : 66187

\*\*\*\*\*  
\*\*\*\*\*

BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax  | Total    |
|------|---------|-------|--------|--------|--------|------|----------|
| I    | PDI     | 54.97 | 840.00 | 0.00   | 79.82  | 0.00 | 974.79   |
| W    | 1013    | 0.00  | 45.00  | 0.00   | 0.00   | 0.00 | 45.00    |
|      | Totals  | 54.97 | 885.00 | 0.00   | 79.82  | 0.00 | 1,019.79 |