



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73446-1
 Promised Date:
 06 JUN 26

73446-1

WO #: 73446-1

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9711 2027 AVENGER
 16BHX
 Serial#: 816041
 Chassis#: 5ZT2AVEC1VG816041
 Miles/Hrs:
 Tag#:
 Purchased Date: 14 JUN 26
 Warranty Date: 18 JUN 26

Date In: 16 JUN 26

Time In:

Job #01 - Warranty

COMPLAINT: ENTRY STRIKER PLATE STICKING.

CAUSE: Entry sticking on the striker plate

CORRECTION: Remove the striker plate, but the two screws
 The striker played in the shop flattened it completely out
 Use two flathead Phillips screws and reattached the striker plate to the door jam
 Tested the door the door now operates correctly and its not hanging up or sticking on the striker plate.
 Request 15 minutes labor

Labor

Job #	Description	Total
01	Entry door adjustment	N/C
Subtotal for Job #01:		0.00

Job #02 - Warranty

COMPLAINT: Gap in sealant at exhaust vent

CAUSE: Unknown

CORRECTION: Found a small gap in the sealant on the bathroom exhaust vent on the roof.
 Use self leveling dicor to seal the gap in the sealant.
 Request 15 minutes labor

Labor

Job #	Description	Total
02	Roof sealant	N/C

Parts

Part #	Description	Qty	Price	Total
49329	DICOR SELF-LEVELING---SEALANT F/EPDM ROOFS	1.00	N/C	N/C

Subtotal for Job #02: 0.00

Job #03 - Warranty

COMPLAINT: Broken U bolt

CAUSE: Unknown

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,

1000

CORRECTION: Remove broken U-bolt from the spare tire carrier
Installed and secured new U-bolt to the spare tire carrier
Request 15 minutes labor

Labor		
Job #	Description	Total
03	Spare tire holder u-bolt	N/C

Subtotal for Job #03: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 16 Jun 2026

W/O: 73446-1
Promised Date: 25 JUN 26

73446-1

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000