



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550257
1 Mi In / 2 Mi Out
In Service Date:
01/01/2017
Sold Date: 04/26/2026
Stock #: KS26-21

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES THE REMOTE THERMOSTATE DOES NOT ENGAGE FURNACE, AC OR FAN	Internal Pay	\$60.00
----	---------------	---	--------------	---------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:05 PM

1. No fix the furnace is controlled by the thermostat in the bedroom not the remote, Requesting .50 for testing

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$60.00

Labor Cost: \$18.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.46	0	0	\$0.00	\$0.00
turnerl	-	0	0.5	0.5	\$60.00	\$18.00
lafavet	-	0	0	0	\$0.00	\$0.00
921	-	0	0	0	\$0.00	\$0.00

1. ac and fan all work like they should when you point the remote at the ac unit, the furnace is controlled by the thermostat in the bedroom and works like it should.

Total Labor Sale
\$60.00

Total Labor Cost
\$18.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES TAPE ON WALL PANELS IN BEDROOM ARE PEELING OFF	Warranty Pay	\$33.00
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:05 PM

1. Tape falling down, needs to be reattached. Requesting .10





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550257

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00

Labor Cost: \$6.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.1	0	0	\$0.00	\$0.00
turnerl	-	0	0.2	0.2	\$33.00	\$6.20
lafavet	-	0	0	0	\$0.00	\$0.00
921	-	0	0	0	\$0.00	\$0.00

1. glued seam tape back on to wall

Total Labor Sale
\$33.00

Total Labor Cost
\$6.20

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C. MISCELLANEOUS	DEALER STATES CEILING PANEL IN KITCHEN HAS A DARK BLEMISH	Warranty Pay	\$0.00
------------------	---	--------------	--------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:05 PM

1. Scarf/blemish in face of ceiling panel. needs new panel approved for 1 hour to touch up

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$27.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.47	0.5	0.5	\$0.00	\$9.50
turnerl	-	0	0.5	0.5	\$0.00	\$18.00
lafavet	-	0	0	0	\$0.00	\$0.00
921	-	0	0	0	\$0.00	\$0.00

1. Seems to be a blemish in he paint on he ceiling panel, tried to clean off but was not doing anything, would need to





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARP22 TE550257	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$27.50

put in a new ceiling panel took pictures or if keystone has a better fix we would have to remove rubber roof and remove the sheeting and a couple trusses to replace ceiling panel.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$27.50	\$0.00	\$0.00

D. MISCELLANEOUS	DEALER STATES PASSENGER SIDE TIRE FENDER AND SHEET METAL ARE NOT SECURED CORRECTLY	Warranty Pay	\$16.50
------------------	--	--------------	---------

Job added by KEVIN GOODIEL on Mon Oct 27, 2025 | 3:05 PM

1. factory never tightened all the way. Requesting.10

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50

Labor Cost: \$3.10

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
boiem	-	0.05	0	0	\$0.00	\$0.00
turnerl	-	0	0.1	0.1	\$16.50	\$3.10
lafavet	-	0	0	0	\$0.00	\$0.00
921	-	0	0	0	\$0.00	\$0.00

1. Screws were loose, tightened screws

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$16.50	\$3.10	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550257

Service Advisor
KEVIN GOODIEL
goodielk

	Category	Sale	Cost
	Labor	\$109.50	\$54.80
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$109.50	\$54.80

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Dec 10, 2025	10:25 AM	10:34 AM	0.15 hrs	I	boiem	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Wed Dec 10, 2025	10:37 AM	10:41 AM	0.05 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Dec 10, 2025	10:52 AM	10:58 AM	0.10 hrs	W	boiem	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Dec 10, 2025	10:59 AM	11:01 AM	0.03 hrs	W	boiem	0.5 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550257

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Dec 10, 2025	11:07 AM	11:14 AM	0.12 hrs	I	boiem	-
Tag: Regular Hour			Reason: -					
C	MISC	Mon Mar 2, 2026	9:44 AM	10:11 AM	0.44 hrs	W	boiem	-
Tag: Regular Hour			Reason: -					
A	MISC	Mon Apr 27, 2026	2:17 PM	2:25 PM	0.13 hrs	I	boiem	-
Tag: Regular Hour			Reason: -					
A	MISC	Mon Apr 27, 2026	2:26 PM	2:29 PM	0.06 hrs	I	boiem	-
Tag: Regular Hour			Reason: -					
A	MISC	-	-	-	0 hrs	I	lafavet	0 hrs
B	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
C	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
D	MISC	-	-	-	0 hrs	W	lafavet	0 hrs
A	MISC	-	-	-	0 hrs	I	turnerl	0.5 hrs
B	MISC	-	-	-	0 hrs	W	turnerl	0.2 hrs
C	MISC	-	-	-	0 hrs	W	turnerl	0.5 hrs
D	MISC	-	-	-	0 hrs	W	turnerl	0.1 hrs
A	MISC	-	-	-	0 hrs	I	921	0 hrs
B	MISC	-	-	-	0 hrs	W	921	0 hrs





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$109.50

RO# : 39861 Tag# : TE550257

Check-in: Mon Oct 27, 2025 | 3:05 PM
Ready for Pickup: Thu Jun 18, 2026 | 10:28 AM
Promise Time: Sat Nov 1, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550257

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	-	-	-	0 hrs	W	921	0 hrs
D	MISC	-	-	-	0 hrs	W	921	0 hrs

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	39861	LINK RV	\$49.50
57200	39861	LINK RV	-\$49.50
67200	39861	LINK RV	\$36.80
14400	boiem	LINK RV	-\$9.50
14400	turnerl	LINK RV	-\$27.30
14400	lafavet	LINK RV	\$0.00
14400	921	LINK RV	\$0.00

Accounting Info - Internal

GL Account #	Control #	Franchise	Amount
14300	KS26-21	LINK RV	\$60.00
57300	39861	LINK RV	-\$60.00
67300	39861	LINK RV	\$18.00
14400	boiem	LINK RV	\$0.00
14400	turnerl	LINK RV	-\$18.00
14400	lafavet	LINK RV	\$0.00
14400	921	LINK RV	\$0.00

