

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66426

Completed : 22 FEB 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10678 Description : 2022 TT COACHMEN CATALINA 263BHCKL
Tag : Date In : 01 FEB 22 Mileage : 0
Author : BH Promised :
Location : 0225 CHECK WORK Date Sched :
Serial# : 5ZT2CARB2NU040038 Chassis# : 5ZT2CARB2NU040038
Warr. Date : Cust PO# :
Print Date : 22 FEB 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: PDI - NEW TRAVEL TRAILER I PDI PRE-D
 CORRECTION: PDI FILLED OUT PAPER WORK
WINT WINTERIZE UNIT AND DRAIN HOLDING TANKS. ***INCLUDES I PDI PRE-D
 2 GALLONS OF ANTI-FREEZE*** UNITS WITH WASHING
 MACHINE OR ICEMAKER WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED
1 COMPLAINT: CLEARANCE LIGHTS STAYING ON ANYTIME THE W 10024 FORES
 7WAY IS PLUGGED INTO THE TRUCK
 CORRECTION: pug in shore cord and clearance lights
 come on, conet up battery and get
 clearance lights on, cut under belly and
 get to 7 way box, check wires conetins
 good, trace green lights wire to back
 left light, traced to back left side
 light and green wire has gray wire
 coneted in, cut gray wire and traced to
 right tail light, reconet wire and start
 pulling lights and testing, front left
 clearance light had gray wire power,
 pull light on outside of slideroom and
 found brown power wire, check power
 wires in harness to slideroom and found
 2 gray wire and a black power wire, go
 inside and pull fuse for slideroom and
 cleanace lights go out, pull inside
 lights out of slideroom and found brown
 power wires, power wire from convter to
 slidroom is black, go under unit and cut
 gray wires to slidroom and test lights
 with out slideroom clearance light lights
 work, right, get inside and finde where
 cleance light is at on outside of wall
 lines up with dinnet base drill hole
 through wall and run new wire from

Continued on page 2

Work Order : 66426

 Job # Description JOB INFORMATION Type Bill To

outside clearance light through wall in
 to dinet base and at floor behind sophia
 to end of slideroom, drill through
 floor of slideroom and run wire down and
 in to wiring harness, conet up to gray
 wires and test light, remount lights and
 cap seal with silacone, put underbelly
 back up and seal curs with tape, put
 inside lights back in slideroom wall and
 ceiling, seal wire holes with silacone

2 COMPLAINT: BLACK TANKS NOT READING ON PANEL W 10024 FORES
 CORRECTION: pull underbelly down and find tank
 wires, test and found ground wire was
 not making coninuity to frame, cut and
 add ground wire to frame and retest, put
 underbelly up

3 COMPLAINT: GREY TANK NOT READING ON PANEL W 10024 FORES
 CORRECTION: pull down underbelly, test wires, splce
 in new ground wire to frame test, put
 underbelly back up

4 THE GREEN COLOR IN THE AWNING STRIP HAS 3 OUT W 10024 FORES
 5 COMPLAINT: SHADE OVER DINNET SCREW PULLED OUT OF W 10024 FORES
 THE WALL
 CORRECTION: remove valance install shade, install
 valance

6 COMPLAINT: RADIO SPEAKERS INSIDE AND OUTSIDE ARE ON W 10024 FORES
 ALL THE TIME AND THE ZONE BUTTONS DOES
 NOT TURN THEM OFF
 CORRECTION: remove radio from cabnet, check wiring do
 a hard rest on radio and test, install
 radio in cabnet

 Job # Part No Description PARTS Bill to Qty Price Total

PDINT	13034	55362 STD BATTERY	I-PDI	1	10.95	10.95
WINTE	24181	-50 RV ANTI-FREEZE	I-PDI	2	4.49	8.98
1	219088	SILICONE II BLACK	W-10024	1	8.04	8.04
4	6576	LED LIGHTS FOR CAR	W-10024	1	135.08	135.08

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	0.27	150.00	40.50
DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	0.67	150.00	100.50
DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	0.71	150.00	106.50
DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	3.04	150.00	456.00
DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	0.29	150.00	43.50
DINTT	Z991	MISC LABOUR CODE (INTE JP	I-PDI	1.02	150.00	153.00

Continued on page 3

Work Order : 66426

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs      Rate      Total
*****
INTER Z990      WINTERIZE UNIT                JP      I-PDI           1.00    130.00    130.00
  1 Z990      MISC LABOUR CODE (EXTE JP    W-10024        2.00    150.00    300.00
  1 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.00    150.00     0.00
  1 Z990      MISC LABOUR CODE (EXTE JP    W-10024        4.00    150.00    600.00
  2 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.30    150.00     45.00
  3 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.30    150.00     45.00
  4 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.00    150.00     0.00
  4 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.50    150.00     75.00
  5 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.00    150.00     0.00
  6 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.20    150.00     30.00
  6 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.00    150.00     0.00
  6 Z990      MISC LABOUR CODE (EXTE JP    W-10024        0.20    150.00     30.00
*****

```

```

*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
DINTT  SS      SHOP SUPPLIES                I-PDI           1.00    35.00    35.00
DINTT  LP20     20 LB. LP CYLINDER          I-PDI           2.00    14.00    28.00
INTER  SS      SHOP SUPPLIES                I-PDI           1.00     9.70     9.70
  4 FRT      UPS-AWN LIGHTS              W-10024         1.00    15.68    15.68
*****

```

CUSTOMER COMMENTS

```

*****
AWNING LIGHTS ARRIVED IN BACKROOM 2-17-22....CAM
ORDERED LIGHTS FOR BEN.
BH GOT APPROVAL GAVE PARTS SHEET TO MATT
BH SENT IN PREAUTH
BH TRIED TO TURN IN PREAUTH BUT THE RADIO JOB DOES NOT SOUND
RIGHT WAITING FOR JAMES
PREAUTH IS A DRAFT AT THIS POINT
*****

```

BILLINGS SUMMARY

```

*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I    PDI           19.93    1030.00      0.00      72.70      0.00    1,122.63
W    10024         143.12    1125.00      0.00      15.68      0.00    1,283.80

Totals           163.05    2155.00      0.00      88.38      0.00    2,406.43
*****

```