



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$313.50

RO# : 40601 Tag# : TE760534

Check-in: Wed May 6, 2026 | 9:47 AM  
Ready for Pickup: Thu Jun 18, 2026 | 10:45 AM  
Promise Time: Mon May 11, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE  
AVALANCHE 366LS  
4YDFAVT22TE760534  
1 Mi In  
Stock #: KS26-40

**Service Advisor**  
BECKY DALEIDEN  
beckl

A.	MISCELLANEOUS	DEALER STATES FRIDGE DOORS ARE OUT OF ADJUSTMENT.	Warranty Pay	\$82.50
----	---------------	---	--------------	---------

Job added by BECKY DALEIDEN on Wed May 6, 2026 | 9:47 AM

1. Styrofoam was wedged creating pressure on door.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.28	0.5	0.5	\$82.50	\$12.00

1. Pulled unit in, hooked up electricity, hooked up battery charger to operate slide outs, opened up unit, inspected fridge, looked for adjustment screws, moved styrofoam and fridge doors lined up as they should. Request 0.5 hours

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$82.50	\$12.00	\$0.00	\$0.00

B.	MISCELLANEOUS	DEALER STATES FURNACE HEATS UP & COOLS DOWN BUT FAN DOESN'T SHUT OFF.	Warranty Pay	\$198.00
----	---------------	---	--------------	----------

Job added by BECKY DALEIDEN on Wed May 6, 2026 | 9:47 AM

1. Faulty circuit board





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$313.50

RO# : 40601 Tag# : TE760534

Check-in: Wed May 6, 2026 | 9:47 AM  
Ready for Pickup: Thu Jun 18, 2026 | 10:45 AM  
Promise Time: Mon May 11, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE  
AVALANCHE 366LS  
4YDFAVT22TE760534

**Service Advisor**  
BECKY DALEIDEN  
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$198.00  
Labor Cost: \$28.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	1.02	1.2	1.2	\$198.00	\$28.80

1. Turned on propane, turned on thermostat, ran it, confirmed it was running with photo of temp gun. Fan continued to run past the usually few minutes. Removed thermostat to inspect wires, disconnected blue wire on thermostat to test switch on loop. Furnace continued to run indicating a possible shorted wire. Removed fireplace to inspect wires, saw no apparent issue, removed access panel in cargo bay to inspect the other side, found no apparent issue, removed furnace exhaust cover, checked bundle of wires wrapped in tape, Found blue wire with questionable "twist on cone" connector, respliced wires with new connector, furnace still did not shut off. Hit power shut off on furnace next to circuit board, furnace fan still did not shut of indicating faulty board. Recommend new circuit board. Request 3 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$198.00	\$28.80	\$0.00	\$0.00

C. MISCELLANEOUS	DEALER STATES SHOWER SLIDING DOOR DOESN'T MOVE FREELY.	Warranty Pay	\$33.00
------------------	--	--------------	---------

Job added by BECKY DALEIDEN on Wed May 6, 2026 | 9:47 AM

1. Broken handle

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$33.00  
Labor Cost: \$4.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.15	0.2	0.2	\$33.00	\$4.80

1. latch/lock appears to be missing components. Recommend new latch. Request 1.0 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$33.00	\$4.80	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$313.50

RO# : 40601 Tag# : TE760534

Check-in: Wed May 6, 2026 | 9:47 AM  
Ready for Pickup: Thu Jun 18, 2026 | 10:45 AM  
Promise Time: Mon May 11, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE  
AVALANCHE 366LS  
4YDFAVT22TE760534

**Service Advisor**  
BECKY DALEIDEN  
beckl

Category	Sale	Cost
Labor	\$313.50	\$45.60
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$313.50</b>	<b>\$45.60</b>

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Jun 17, 2026	2:24 PM	2:41 PM	0.28 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	2:41 PM	3:37 PM	0.92 hrs	W	matthewl	1.2 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	3:37 PM	3:42 PM	0.10 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
C	MISC	Wed Jun 17, 2026	3:45 PM	3:55 PM	0.15 hrs	W	matthewl	0.2 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$313.50**

**RO# : 40601 Tag# : TE760534**

Check-in: Wed May 6, 2026 | 9:47 AM  
Ready for Pickup: Thu Jun 18, 2026 | 10:45 AM  
Promise Time: Mon May 11, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 KEYSTONE  
AVALANCHE 366LS  
4YDFAVT22TE760534

**Service Advisor**  
BECKY DALEIDEN  
beckl

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40601	LINK RV	\$313.50
57200	40601	LINK RV	-\$313.50
67200	40601	LINK RV	\$45.60
14400	matthewl	LINK RV	-\$45.60

